

HISTORIC CHARLESTON FOUNDATION
HURRICANE HUGO DAMAGE ASSESSMENT FORM

Date of Survey: 11/2/89

Video: Reel/Frame

Camera:

Survey Team: RWC
Members:

Slides: []
B. & W.: []

Name of Property: (if any)

Street Address: 13 NEW ST.

Tax Map Number: 457-12-3-103

Current Owner:

DESCRIPTION

Principal Building ☒ Dependency ☐ Other ☐

No. of Stories: Basement ☐ 1 ☐ 2 ☒ 3 ☐ 4 ☐
Attic or Half Story ☐

Material:

Structure: Brick ☐ Wood Frame ☒ Stone ☐ Metal ☐
Other ☐:

Surface Covering: Stucco ☐ Wood Siding ☒ Other ☐:

Roof Covering: Slate ☐ Metal ☐ Tile ☐ Asphalt ☐
Other ☐: FLAT TO LOW HIP

Piazza: Foundation: Brick ☒ Stone ☐ Wood ☐
Other ☐:

Main Piazza: Brick ☐ Wood ☒ Other ☐

Roof Covering (if different from main building):

Chimneys: Brick ☒ Brick & Stucco ☒ Stone ☐ Other ☐

Comments:

Address:

Tax Map No.:

Page 2

Damage Assessment

None

Minor

Major

%

Exterior Features

Walls: Foundation/Basement	[]	[X]	[]
1st Floor	[]	[X]	[]
2nd Floor	[]	[X]	[]
3rd Floor	[]	[]	[]
4th Floor	[]	[]	[]
Attic	[]	[]	[]
Doors	[X]	[]	[]
Windows	[X]	[]	[]
Shutters			
Piazza/Portico	[]	[X]	[]
Downspouts	[X]	[]	[]
Gutters	[]	[X]	[]
Cornice	[]	[X]	[]
Parapet	[]	[]	[]
Roof Covering	[]	[]	[]
Dormers (Number: 0)	[]	[]	[]
Chimneys (Number: 2)	[X]	[]	[]

Other Visible Damage

Garden Walls/Fences	[X]	[]	[]
Gates	[X]	[]	[]
Walkways/Paving	[X]	[]	[]
Sidewalks	[X]	[]	[]
Trees	[X]	[]	[]
Mechanical	[X]	[]	[]