

1886 Earthquake Damage Assessment

Owner & Occupant	Material		Dimensions			Condition of Walls				Condition of Chimneys or Flues	\$ Damages by Earthquake	
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West			
138 Wentworth J.H. Bennecker Dwelling	Brick	Tin	50	40	35	Badly cracked	Tops down and cracked	Cracked	Cracked	[not recorded]	\$ 850	
What should be done to make it safe	Remarks											
Repair cracks; rebuild north wall and parapets and porch on south.	[none recorded]											

Cite as: Record of Earthquake Damages, 1886. On microfiche, Historic Charleston Foundation Archives.