

Owner & Occupant	Material		Dimensions				Condition of Walls				Condition of Chimneys or Flues	Damages by Earthquake (\$)
	Building	Roof	Ft. Long	Ft. Wide	Ft. High		North	South	East	West		
Sisters of Our Lady of Mercy, School	Brick	Slate	150	60	55		Good	Good	Badly cracked	Cracked over openings	Good	2500

Nathaniel Russell House
51 Meeting St.

What should be done to make it safe	Remarks
Has been anchored from north to south and east to west; it was badly sprung and separated.	Stable badly cracked.