

HISTORIC CHARLESTON FOUNDATION  
HURRICANE HUGO DAMAGE ASSESSMENT FORM

Date of Survey: 10/16/89

Video: Reel/Frame

Camera:

Survey Team: S.O.B. #2

Slides: [I. 24]

Members:

B. & W.: [7/15/89]

Huggins, Mark,  
Saylor, Reynolds

Name of Property: (if any)

Street Address: 16 Water

Tax Map Number: 488-13-1-27

Current Owner:

DESCRIPTION

Principal Building ☒ Dependency ☐ Other ☐

No. of Stories: Basement ☒ 1 ☐ 2 ☒ 3 ☐ 4 ☐

Attic or Half Story ☒

Material:

Structure: Brick ☐ Wood Frame ☒ Stone ☐ Metal ☐  
Other ☐:

Surface Covering: Stucco ☐ Wood Siding ☒ Other ☐:

Roof Covering: Slate ☒ Metal ☐ Tile ☐ Asphalt ☐  
Other ☐:

Piazza: none Foundation: Brick ☒ Stone ☐ Wood ☐  
Other ☐:

Main Piazza: Brick ☐ Wood ☐ Other ☐

Roof Covering (if different from main building):

Chimneys: Brick ☒ Brick & Stucco ☐ Stone ☐ Other ☐

Comments:

Address: 14 Water

Tax Map No.:

Page 2

Damage Assessment

None

Minor

Major

%

## Exterior Features

Walls: Foundation/Basement

[✓]

[ ]

[ ]

1st Floor

[✓]

[ ]

[ ]

2nd Floor

[ ]

[ ]

[ ]

3rd Floor

[ ]

[ ]

[ ]

4th Floor

[ ]

[ ]

[ ]

Attic

[✓]

[ ]

[ ]

Doors

[✓]

[ ]

[ ]

Windows

[ ]

[✓]

[ ]

2%

(broken panes, not frames)

Shutters

✓

Piazza/Portico

[ ]

[ ]

[ ]

Downspouts

[✓]

[ ]

[ ]

Gutters

[✓]

[ ]

[ ]

Cornice

[✓]

[ ]

[ ]

Parapet

[ ]

[ ]

[ ]

Roof Covering

[ ]

[✓]

[ ]

5%

Dormers (Number: 0)

[ ]

[ ]

[ ]

Chimneys (Number: 1)

[✓]

[ ]

[ ]

## Other Visible Damage

Garden Walls/Fences

[✓]

[ ]

[ ]

Gates

[✓]

[ ]

[ ]

Walkways/Paving

[✓]

[ ]

[ ]

Sidewalks

[✓]

[ ]

[ ]

Trees

[✓]

[ ]

[ ]

Mechanical

[ ]

[ ]

[ ]

N.A.

