

Owner & Occupant	Material		Dimensions			Condition of Walls				Condition of Chimneys or Flues	Damages by Earthquake (\$)
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West		
Est. of John Forrest, dwelling	Frame	Tin	40	25	35	←	FRAME	GOOD	→	Tops down, foundation cracked	\$ 75

What should be done to make it safe	Remarks
Rebuild chimneys from below ceiling joists.	[none recorded]

10 King St.