

Owner & Occupant	Material		Dimensions			Condition of Walls				Condition of Chimneys or Flues	Damages by Earthquake (\$)
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West		
Mrs. R. R. White, dwelling	Frame	Slate	32	16	25	Frame Good				Good	[none]

16 Water Street

What should be done to make it safe	Remarks
"O.K."	

Cite as: *Record of Earthquake Damages, 1886*. On microfiche, Historic Charleston Foundation Archives.