

HISTORIC CHARLESTON FOUNDATION
HURRICANE HUGO DAMAGE ASSESSMENT FORM

Date of Survey: 17 Oct 1989

Video: Reel/Frame

Camera:

Survey Team:
Members:

Slides: []
B. & W.: []

Name of Property: (if any)

Street Address: 35 Chapel St.

Tax Map Number: 459-13-1 #79

Current Owner:

DESCRIPTION

Principal Building [☒] Dependency [] Other []

No. of Stories: Basement [] 1 [] 2 [☒] 3 [] 4 []

Attic or Half Story [☒]

Material:

Structure: Brick [] Wood Frame [☒] Stone [] Metal []
Other []:

Surface Covering: Stucco [] Wood Siding [☒] Other []:

Roof Covering: Slate [] Metal [☒] Tile [] Asphalt []
Other []:

Piazza: Foundation: Brick [☒] Stone [] Wood []
Other []:

Main Piazza: Brick [] Wood [☒] Other []

Roof Covering (if different from main building):

Chimneys: Brick [] Brick & Stucco [☒] Stone [] Other []

Comments:

Address:

Tax Map No.:

Page 2

Damage Assessment

None

Minor Major

%

Exterior Features

Walls: Foundation/Basement	[X]	[]	[]	
1st Floor	[X]	[]	[]	
2nd Floor	[X]	[]	[]	
3rd Floor	[]	[]	[]	
4th Floor	[]	[]	[]	
Attic	[X]	[]	[]	
Doors	[X]	[]	[]	
Windows	[X]	[]	[]	
Shutters	/			
Piazza/Portico	[X]	[]	[]	
Downspouts	[]	[X]	[]	5%
Gutters	[]	[X]	[]	5%
Cornice	[X]	[]	[]	
Parapet	[]	[]	[]	
Roof Covering	[]	[X]	[]	15%
Dormers (Number: 0)	[]	[]	[]	
Chimneys (Number: 2) one w/ [X]	[X]	[]	[]	15%

Other Visible Damage

Garden Walls/Fences	[X]	[]	[]
Gates	[X]	[]	[]
Walkways/Paving	[X]	[]	[]
Sidewalks	[X]	[]	[]
Trees	[X]	[]	[]
Mechanical	[X]	[]	[]

