

Owner & Occupant	Material		Dimensions			Condition of Walls				Condition of Chimneys or Flues	Damages by Earthquake (\$)
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West		
John Kucker, Dwelling	Brick	Tile	30	[not recorded]	40	Good	Good	Good	Good	Have been rebuilt	[none listed]

What should be done to make it safe	Remarks
Cracks in west wall have been rebuilt with new work	[none listed]

36 Coming St.

Cite as: Record of Earthquake Damages, 1886. On microfiche, Historic Charleston Foundation Archives.

✓

✓

HISTORIC CHARLESTON FOUNDATION
HURRICANE HUGO DAMAGE ASSESSMENT FORM

Date of Survey: 10.18.89

Video: Reel/Frame

Camera:

Slides: [21] R-2

B. & W.: [21] R-2

Survey Team: CHARLESTON

Members: Disk, Rosenthal, Shepard

Name of Property: (if any)

Street Address: 36 COMING

Tax Map Number: 457-4-1-27

Current Owner:

DESCRIPTION

Principal Building [X] Dependency [] Other []

No. of Stories: Basement [] 1 [] 2 [] 3 [] 4 []

Attic or Half Story [X]

Material:

Structure: Brick [] Wood Frame [] Stone [] Metal []
Other [X]: STUCCO MASONRY

Surface Covering: Stucco [X] Wood Siding [] Other []:

Roof Covering: Slate [] Metal [X] Tile [] Asphalt []
Other []:

Piazza: Foundation: Brick [] Stone [] Wood []
Other [X]: STUCCO MASONRY

Main Piazza: Brick [] Wood [X] Other []

Roof Covering (if different from main building):

Chimneys: Brick [X] Brick & Stucco [] Stone [] Other []

Comments:

Address:

Tax Map No.:

Page 2

Damage Assessment None Minor Major %

Exterior Features

Walls: Foundation/Basement 1st Floor 2nd Floor 3rd Floor 4th Floor Attic Doors Windows

Shutters

Piazza/Portico Downspouts Gutters Cornice Parapet Roof Covering Dormers (Number: 3) Chimneys (Number: 2)

Other Visible Damage

Garden Walls/Fences Gates Walkways/Paving Sidewalks Trees Mechanical



36 Coming Street After Hurricane Hugo; photo by Historic Charleston foundation