

Owner & Occupant	Material		Dimensions			Condition of Walls				Condition of Chimneys or Flues	Damages by Earthquake (\$)
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West		
Dwelling (no owner listed)	Brick	Slate	35	22	24	Good	Good	Good	Cracked	Now good; has been rebuilt	150

What should be done to make it safe	Remarks
Have plastered west wall	

70 coming

✓

HISTORIC CHARLESTON FOUNDATION
HURRICANE HUGO DAMAGE ASSESSMENT FORM

Date of Survey: 10-18-89

Video: Reel/Frame

Survey Team: SISK, ROSENTHAL
Members: SHEPHERD

Camera:

Slides: [18] [1000]
B. & W.: [] [1000]

HARLESTON

Name of Property: (if any)

Street Address: 70 COMING

Tax Map Number: 457-4-1-1

Current Owner:

DESCRIPTION

Principal Building ☒ Dependency ☐ Other ☐

No. of Stories: Basement ☐ 1 ☐ 2 ☐ 3 ☒ 4 ☐

Attic or Half Story ☐

Material:

Structure: Brick ☐ Wood Frame ☐ Stone ☐ Metal ☐
Other ☒: STUCCO W/ STONE

Surface Covering: Stucco ☒ Wood Siding ☐ Other ☐:

Roof Covering: Slate ☐ Metal ☐ Tile ☐ Asphalt ☒ SHINGLE
Other ☐:

Piazza: Foundation: Brick ☐ Stone ☐ Wood ☐
Other ☒: STUCCO W/ STONE

Main Piazza: Brick ☐ Wood ☒ Other ☐

Roof Covering (if different from main building):

Chimneys: Brick ☐ Brick & Stucco ☒ Stone ☐ Other ☐

Comments:

PINZZA CORNICE DAMAGE Long R-?

WALLS HAVE MISSING STUCCO & RECESSES
SUCH AS HUGO DAMAGE

Address:

Tax Map No.:

Page 2

Damage Assessment

None

Minor

Major

%

Exterior Features

Walls: Foundation/Basement

☒☐☐

1st Floor

☒☐☐

2nd Floor

☒☐☐

3rd Floor

☒☐☐

4th Floor

☐☐☐

Attic

☐☐☐

Doors

☒☐☐

Windows

☒☐☐Shutters

Piazza/Portico

☒☐☐

Downspouts

☐☒☐

Gutters

☐☒☐

← Cornice

☒☐☐

Parapet

☒☐☐

Roof Covering

☒☐☐~~Dormers (Number:)~~~~☐~~~~☐~~~~☐~~

Chimneys (Number:)

☒☐☐

Other Visible Damage

Garden Walls/Fences

☒☐☐

Gates

☒☐☐

Walkways/Paving

☒☐☐

Sidewalks

☒☐☐

- Trees

☐☒☐

Mechanical

☐☐☐

