

Owner & Occupant	Material		Dimensions			Condition of Walls				Condition of Chimneys or Flues	Damages by Earthquake (\$)
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West		
Dwelling (no occupant listed)	Brick	Slate	35	22	24	Good	Cracked	Cracked	Cracked	Good	450

What should be done to make it safe	Remarks
Veranda down; must be replaced and all cracks repaired; top part of west wall has been rebuilt	

72 Conning

Cite as: Record of Earthquake Damages, 1886. On microfiche, Historic Charleston Foundation Archives.

HISTORIC CHARLESTON FOUNDATION  
HURRICANE HUGO DAMAGE ASSESSMENT FORM

Date of Survey: 10/18/1989

Video: Reel/Frame

Camera:

Survey Team: HARLESTON

Slides: [ 17 ] Roll 2

Members: SHEPARD / SISK / Rosenthal

B. & W.: [ 17 ] Roll 2

Name of Property: (if any)

Street Address: 72 COMING

Tax Map Number: 457-4-1-1

Current Owner:

DESCRIPTION

Principal Building ☒ Dependency ☐ Other ☐

No. of Stories: Basement ☐ 1 ☐ 2 ☒ 3 ☐ 4 ☐

Attic or Half Story ☒

Material:

Structure: Brick ☐ Wood Frame ☐ Stone ☐ Metal ☐  
Other ☒: STUCCO MESS

Surface Covering: Stucco ☒ Wood Siding ☐ Other ☐:

Roof Covering: Slate ☐ Metal ☐ Tile ☐ Asphalt ☐  
Other ☐: UNDER REPAIR

Piazza: Foundation: Brick ☐ Stone ☐ Wood ☐  
Other ☒: STUCCO MESS

Main Piazza: Brick ☐ Wood ☐ Other ☒ STUCCO MESS  
WOOD SIDING

Roof Covering (if different from main building):  
ASPHALT STUCCO

Chimneys: Brick ☐ Brick & Stucco ☒ Stone ☐ Other ☐

Comments:

Address:

Tax Map No.:

Page 2

Damage Assessment

None

Minor

Major

%

## Exterior Features

Walls: Foundation/Basement	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
1st Floor	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2nd Floor	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<del>3rd Floor</del>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<u>4th Floor</u>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Attic	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Doors	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Windows	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Shutters	<input checked="" type="checkbox"/>		
Piazza/Portico	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Downspouts	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Gutters	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Cornice	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Parapet	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Roof Covering	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/> <i>SLATE</i>
Dormers (Number: 2)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Chimneys (Number: 2)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

## Other Visible Damage

Garden Walls/Fences	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Gates	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Walkways/Paving	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Sidewalks	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Trees	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Mechanical ?	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>