

4 Gadsden Street
Documentation of Fire Damage
(2017.016.1)

Filename	Description
045	First floor, SW room and mid-south room (triple parlor)
046	First floor, looking from west to east
047	First floor west room, looking west
048	First floor west room, looking east
051	Looking up where central chimney had been
052	Lath behind the chimney
053	Cavity behind the chimney (first floor)
054	Behind the chimney
055	Looking down the chimney
056	First floor, far east room looking east of triple parlor
057	First floor, far east room looking east of triple parlor
058	First floor, far east room looking northwest of triple parlor
062	Doorway of east room looking north to 1910s addition
064	North addition bathroom
067	First floor east room looking southwest
073	First floor bedroom looking west to main entrance
075	Central hallway looking west
076	Main entrance looking west
077	Looking up stairway
079	Looking down stairway to main entrance
081	Behind the chimney, second floor
085	Second floor, far east room looking east
086	Second floor, far east room looking southeast
087	Second floor, far east room looking southwest
088	Second floor, far east room looking northwest
089	Second floor, far east room looking northeast
090	Porches looking west
091	Porches looking East (Baker House in background)
092	Second floor, west room looking north
093	Second floor, west room looking south
094	Second floor, west room looking north
101	Stairway going to the third floor
102	Second floor hallway
103	Looking south in central rooms of second floor
104	Looking south in central rooms of second floor
106	Second floor, central room looking north
107	Second floor, central room looking west-southwest
108	Second floor, central room looking north
110	Second floor, central room looking southeast
117	Exterior (north side) where additions had been, looking west (additions came off in the fire)
119	Fire escape to third floor
121	Third floor looking west along north side
124	Third floor, east room looking south
125	Third floor, east room looking north

4 Gadsden Street
Documentation of Fire Damage
(2017.016.1)

Filename	Description
126	Third floor, east room looking west
132	Third floor, east room looking south
133	Third floor porch looking west
134	Third floor porch looking east
135	Third floor, central room looking north
136	Third floor, central room looking northeast
137	Third floor, central room looking east
139	Stairhall looking north (stairs under board)
140	Stairhall looking north
141	Looking down the chimney, third floor
151	Third floor, far west bedroom
152	Third floor, far west bedroom
154	Third floor, far west room looking southeast
155	Third floor, far west room looking northeast
156	Third floor, far west room looking east
162	Roof after replacement and new brick parapet looking northeast
163	Roof after replacement and new brick parapet looking east
165	Looking down from the roof at the additions that were later torn off
167	View from the roof looking east
168	View from the roof looking west; Baker House in background
177	View of entry gate from Beaufain Street
179	View of porches, south side
180	Basement looking west
181	Basement looking east
182	Looking south from the basement to Beaufain Street
183	View of porches, south elevation
184	View of porches looking north
185	View of front of house looking east
186	View of front of house looking east
187	Doorway
188	Looking north at the basement doorway
190	Looking up the building at the piazzas
191	Looking up the building at the piazzas
196	Central basement room looking north
197	Far east basement room looking north
198	Far west basement room looking north (fire started here)
199	West elevation
200	View from the corner of Gadsden and Beaufain looking northeast
DSC02669	West elevation
DSC02682	Central room molding with "heaven" theme
DSC02683	Looking south at central room molding with "heaven" theme
DSC02685	West room looking southwest
DSC02693	Rear (east elevation)
DSC02700	Source of fire, far west basement

4 Gadsden Street
Documentation of Fire Damage
(2017.016.1)

Filename	Description
DSC02732	Central second floor main room looking east
DSC02733	Central second floor main room looking south
DSC02734	Central second floor main room looking south
DSC02743	Second floor west room looking west
004	View from the roof looking west
005	View from the roof looking south; Sgt. Jasper in background
007	View from the roof looking north
008	View from the roof looking west
009	Looking down the chimney (before demolition)
016	View from the roof looking east days after the fire (Baker House in background)
028	Looking down the stairway from the second floor
033	Cast iron Temple of Wind columns at front entrance
035	View of the front entrance gate
037	Steps to the front entrance
038	Looking east into the main entrance foyer from the top of the outside main steps
040	First (main) floor looking east down the central hallway from the entrance foyer
041	Looking up and east towards the second floor of the central stairway, showing the temporary steps built after the original collapsed due to the fire
044	Medallions from the second floor windows