

Owner & Occupant	Material		Dimensions			Condition of Walls				Condition of Chimneys or Flues	Damages by Earthquake (\$)
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West		
DR. A. SIMONDS, DWELLING	BRICK	SLATE	50	40	50	✓G	0	0	D>	REBUILT	\$500

What should be done to make it safe	Remarks
"Now Good."	

20 SOUTH BATTERY