

Owner & Occupant	Material		Dimensions			Condition of Walls				Condition of Chimneys or Flues	Damages by Earthquake (\$)
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West		
Devereaux & McBurney, office	Brick	slate	36	22	45	OK	OK	OK	OK	OK	/

What should be done to make it safe	Remarks
OK	

29 Broad St.