

Owner & Occupant	Material		Dimensions			Condition of Walls				Condition of Chimneys or Flues	Damages by Earthquake (\$)
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West		
Wm. Rieppe, Dwelling	Frame	Shingle	50	25	35	G	O	O	D	GOOD	n/a

What should be done to make it safe	Remarks

HISTORIC CHARLESTON FOUNDATION
HURRICANE EUGO DAMAGE ASSESSMENT FORM

Date of Survey: July 12, 1990
Survey Team:
Members: CL LM
EK

Video: Real/Frame

Camera:

Slides: []

B. & W.: []

Name of Property: (if any)

Street Address: 58 George St

Tax Map Number: 457-4-2-43

Current Owner: CofC

DESCRIPTION

Principal Building ☒ Dependency [] Other []

No. of Stories: Basement ☒ 1 [] 2 ☒ 3 [] 4 []

Attic or Half Story ☒

Material:

Structure: Brick [] Wood Frame ☒ Stone [] Metal []
Other []:

Surface Covering: Stucco [] Wood Siding ☒ Other []:

Roof Covering: Slate [] Metal ☒ Tile [] Asphalt []
Other []:

Piazza: Foundation: Brick [] Stone [] Wood []
Other []:

N/A Main Piazza: Brick [] Wood [] Other []

Roof Covering (if different from main building):

Chimneys: Brick ☒ Brick & Stucco [] Stone [] Other []

Comments:

Address:

Tax Map No.:

Page 2

Damage Assessment

None

Minor

Major

\$

Exterior Features

Walls: Foundation/Basement

☒☐☐

1st Floor

☒☐☐

2nd Floor

☒☐☐

3rd Floor

☐☐☐

4th Floor

☐☐☐

Attic

☒☐☐

Doors

☒☐☐

Windows

☐☒☐

Shutters

Piazza/Portico

☒☐☐

Downspouts

☒☐☐

Gutters

☒☐☐

Cornice

☒☐☐

Parapet

☒☐☐

Roof Covering

☒☐☐

Dormers (Number: 2)

☐☒☐

Chimneys (Number: 2)

☒☐☐

Other Visible Damage

Garden Walls/Fences

☒☐☐

Gates

☒☐☐

Walkways/Paving

☒☐☐

Sidewalks

☒☐☐

Trees

☒☐☐

Mechanical

☒☐☐

W/A

3000

1000