

Owner & Occupant	Material		Dimensions			Condition of Walls			Condition of Chimneys or Flues	Damages by Earthquake (\$)
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East		
J. D. Murphy, dwelling	Frame	Tin	50	30	40	Good	Good	Good	Good	Slightly cracked but appear safe
What should be done to make it safe	Remarks									
"O.K."	30 Mary Street									

Cite as: Record of Earthquake Damages, 1886. On microfiche, Historic Charleston Foundation Archives.