

Owner & Occupant	Material		Dimensions			Condition of Walls				Condition of Chimneys or Flues	Damages by Earthquake (\$)
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West		
Mrs. D. Gehlkn, Dwelling	Frame	Shingle	40	30	(not recorded)	Good	Good	Good	Good	(not recorded)	\$38

What should be done to make it safe	Remarks
	(not recorded)

85 Tradd St.