

Owner & Occupant	Material	Dimensions			Condition of Walls			Condition of Chimneys or Flues	Damages by Earthquake (\$)		
		Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West	
Hannah Ishm, Vacant	Brick	Tin	50	25	35	6 good	6 good	Slightly cracked	Badly cracked	Could not get in to examining	—

What should be done to make it safe
Remarks

Has been anchored and repaired
Kitchen in rear
Slightly cracked

Cite as: Record of Earthquake Damages, 1886. On microfiche. Historic Charleston Foundation Archives.

188 King