

HISTORIC CHARLESTON FOUNDATION
HURRICANE HUGO DAMAGE ASSESSMENT FORM

Date of Survey: 11.28.89

Video: Reel/Frame

Survey Team:
Members:

SOB

Camera:

Slides: []

B. & W.: []

Name of Property: (if any)

Street Address:

85 TRADD

Tax Map Number:

457-16-2-3

Current Owner:

DESCRIPTION

Principal Building ☒ Dependency ☐ Other ☐

No. of Stories: Basement ☒ 1 ☐ 2 ☒ 3 ☐ 4 ☐
Attic or Half Story ☒

Material:

Structure: Brick ☐ Wood Frame ☒ Stone ☐ Metal ☐
Other ☐:

Surface Covering: Stucco ☐ Wood Siding ☒ Other ☐:

Roof Covering: Slate ☐ Metal ☐ Tile ☐ Asphalt ☐
Other ☐:

Piazza: Foundation: Brick ☐ Stone ☐ Wood ☐
Other ☐:

NX Main Piazza: Brick ☐ Wood ☐ Other ☐

Roof Covering (if different from main building):

Chimneys: Brick ☐ Brick & Stucco ☒ Stone ☐ Other ☐

Comments:

Address:

Tax Map No.:

Page 2

Damage Assessment

None

Minor

Major

%

Exterior Features

Walls: Foundation/Basement	[]	[]	[]
1st Floor	<input checked="" type="checkbox"/>	[]	[]
2nd Floor	<input checked="" type="checkbox"/>	[]	[]
3rd Floor	[]	[]	[]
4th Floor	[]	[]	[]
Attic	<input checked="" type="checkbox"/>	[]	[]
Doors	[]	[]	[]
Windows	<input checked="" type="checkbox"/>	[]	[]
Shutters	<input checked="" type="checkbox"/>		
Piazza/Portico	NA []	[]	[]
Downspouts	<input checked="" type="checkbox"/>	[]	[]
Gutters	<input checked="" type="checkbox"/>	[]	[]
Cornice	<input checked="" type="checkbox"/>	[]	[]
Parapet	NA []	[]	[]
Roof Covering	<input checked="" type="checkbox"/>	[]	[]
Dormers (Number: NA)	[]	[]	[]
Chimneys (Number: 2)	<input checked="" type="checkbox"/>	[]	[]

Other Visible Damage

Garden Walls/Fences	NA []	[]	<input checked="" type="checkbox"/> 50%
Gates	NA []	[]	[]
Walkways/Paving	<input checked="" type="checkbox"/>	[]	[]
Sidewalks	<input checked="" type="checkbox"/>	[]	[]
Trees	[]	[]	[]
Mechanical	[]	[]	[]

has
already
been
replaced