

Owner & Occupant	Material		Dimensions			Condition of Walls				Condition of Chimneys or Flues	Damages by Earthquake (\$)	What should be done to make it safe	Remarks
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West				
39 Meeting Vacant dwelling	Brick	Tile	—	—	—	Good	Good	Down, now boarded	Slightly cracked over openings	chimneys down; must be restored	700	Restore east wall; repair west wall and rebuild chimneys 9 feet below roof.	Brick kitchen total wreck

Cite as: Record of Earthquake Damages, 1886. On microfiche, Historic Charleston Foundation Archives

HISTORIC CHARLESTON FOUNDATION  
HURRICANE HUGO DAMAGE ASSESSMENT FORM

Date of Survey: 10/17/89

Video: Reel/Frame

Camera:

Slides: [2.17]

B. & W.: [3.30, 21]

Survey Team: Job #2

Members: *Hobins, March,  
Saylor, Reynolds*

Name of Property: (if any)

Street Address: 39 Meeting Street

Tax Map Number: 457-16-2-20

Current Owner:

DESCRIPTION

Principal Building  Dependency  Other

No. of Stories: Basement  1  2  3  4

Attic or Half Story

Material:

Structure: Brick  Wood Frame  Stone  Metal   
Other :

Surface Covering: Stucco  Wood Siding  Other :

Roof Covering: Slate  Metal  Tile  Asphalt   
Other :

Piazza: Foundation: Brick  Stone  Wood   
Other :

Main Piazza: Brick  Wood  Other  Stucco

Roof Covering (if different from main building):

Chimneys: Brick  Brick & Stucco  Stone  Other

Comments:

*This dwelling is currently undergoing renovation.*

Address: 39 Meeting St

Tax Map No.: 457-16-2-20

Page 2

## Damage Assessment

None

Minor

Major

%

## Exterior Features

Walls: Foundation/Basement

1st Floor

2nd Floor

3rd Floor

4th Floor

Attic

Doors

Windows

Shutters

Piazza/Portico

Downspouts

Gutters

 1070

Cornice

Parapet

Roof Covering

 2070

Dormers (Number: 1)

Chimneys (Number: 4)

2570

one chimney damage

## Other Visible Damage

Garden Walls/Fences

Gates

Walkways/Paving

Sidewalks

Trees

Mechanical

