

HISTORIC CHARLESTON FOUNDATION
HURRICANE HUGO DAMAGE ASSESSMENT FORM

Date of Survey: 10-18-89 -

Video: Reel/Frame

Camera:

Survey Team: MUC
Members:

Slides: []

B. & W.: []

Name of Property: (if any)

Street Address: 29 TRAD

Tax Map Number: 458-13-1-38

Current Owner:

DESCRIPTION

Principal Building [☒] Dependency [] Other []

No. of Stories: Basement [] 1 [] 2 [☒] 3 [] 4 []

Attic or Half Story [☒]

Material:

Structure: Brick [] Wood Frame [☒] Stone [] Metal []
Other []:

Surface Covering: Stucco [] Wood Siding [☒] Other []:

Roof Covering: Slate [] Metal [] Tile [] Asphalt []
Other []: Blown off: now covered in felt paper

Piazza: Foundation: Brick [☒] Stone [] Wood []
Other []:

Main Piazza: Brick [] Wood [] Other []

Roof Covering (if different from main building):

Chimneys: Brick [] Brick & Stucco [☒] Stone [] Other []

Comments:

Address: 29 Tradd

Tax Map No.: 458-13-1-38

Page 2

Damage Assessment

None

Minor

Major

%

Exterior Features

Walls: Foundation/Basement

[-]

[]

[]

1st Floor

[✓]

[]

[]

2nd Floor

[✓]

[]

[]

3rd Floor

[✓]

[]

[]

4th Floor

[✓]

[]

[]

Attic

[✓]

[]

[]

Doors

[✓]

[]

[]

Windows

[✓]

[]

[]

Shutters

[✓]

[]

[]

Piazza/Portico

[✓]

[]

[]

Downspouts

[✓]

[]

[]

Gutters

[]

[]

[]

Cornice

[]

[]

[]

Parapet

[]

[]

[]

Roof Covering

[]

[]

[✓] 100%

Dormer's (Number:)

[]

[]

[]

Chimneys (Number:)

[✓]

[]

[]

Other Visible Damage

Garden Walls/Fences

[✓]

[]

[]

Gates

[✓]

[]

[]

Walkways/Paving

[✓]

[]

[]

Sidewalks

[✓]

[]

[]

Trees

[✓]

[]

[]

Mechanical

[✓]

[]

[]



