

# 1886 Earthquake Damage Assessment

Owner & Occupant	Material		Dimensions			Condition of Walls				Condition of Chimneys or Flues	Damages by Earthquake (\$)
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West		
H. Viohl, Store & dwelling	Brick	Slate	40	20	35	Division	Badly cracked	Division	Slightly cracked	Good	150 *

What should be done to make it safe	Remarks
Anchor east & west walls at floors at each story	

82 Church St.

Per two currency conversion websites,

150 = 5,132.68

= 4,046.10

in 2016 dollars

HISTORIC CHARLESTON FOUNDATION  
HURRICANE HUGO DAMAGE ASSESSMENT FORM

Date of Survey: 10/7/89

Video: Reel/Frame

Survey Team:

Camera:

Members:

SDB

Slides: [ 1 ]

B. & W.: [ 2 ]

Name of Property: (if any)

Street Address: 82<sup>84</sup>-CHURCH ST

Tax Map Number: 468-9-3-78

Current Owner:

DESCRIPTION

Principal Building ☒ Dependency [ ] Other [ ]

No. of Stories: Basement ☒ 1 [ ] 2 [ ] 3 ☒ 4 [ ]

Attic or Half Story [ ]

Material:

Structure: Brick ☒ Wood Frame [ ] Stone [ ] Metal [ ]  
Other [ ]:

Surface Covering: Stucco ☒ Wood Siding [ ] Other [ ]:

Roof Covering: Slate [ ] Metal [ ] Tile [ ] Asphalt [ ]  
<sup>not</sup> Other [ ]:

Piazza: Foundation: Brick [ ] Stone [ ] Wood [ ]  
Other [ ]:

Main Piazza: Brick [ ] Wood [ ] Other [ ]

Roof Covering (if different from main building):

Chimneys: Brick [ ] Brick & Stucco ☒ Stone [ ] Other [ ]

Comments:

Address: 82 Church St. Tax Map No.: 454- 9-3- 78

Page 2

Damage Assessment

None

Minor

Major

8

## Exterior Features

Walls: Foundation/Basement	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
1st Floor	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/> <i>Structural damage 10%</i>
2nd Floor	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3rd Floor	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4th Floor	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Attic	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Doors	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Windows	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Shutters			
Piazza/Portico	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Downspouts	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Gutters	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Cornice	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Parapet	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Roof Covering <i>not vis</i>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Dormers (Number: 0)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Chimneys (Number: 2)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

## Other Visible Damage

Garden Walls/Fences	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Gates	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Walkways/Paving	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Sidewalks	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Trees	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Mechanical	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>



82-84 Church Street After Hurricane Hugo