

Owner & Occupant	Material		Dimensions			Condition of Walls				Condition of Chimneys or Flues	Damages by Earthquake (\$)
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West		
St. Michael's Church, Dwelling	Brick	slate	36	20	30			Repaired		Repaired	395

What should be done to make it safe	Remarks
O.K.	

97 Wentworth

Cite as: Record of Earthquake Damages, 1886. On microfiche, Historic Charleston Foundation Archives.

HISTORIC CHARLESTON FOUNDATION
HURRICANE HUGO DAMAGE ASSESSMENT FORM

Date of Survey: 12 JULY 1990

Survey Team:

Members:

EK/LM/CL

Video: Reel/Frame

Camera:

Slides: []

B. & W.: []

Name of Property: (if any)

Street Address: 97 WENTWORTH

Tax Map Number: 457-4-93-4

Current Owner:

DESCRIPTION

Principal Building ☒ Dependency ☐ Other ☐

No. of Stories: Basement ☐ 1 ☐ 2 ☒ 3 ☐ 4 ☐

Attic or Half Story ☒

Material:

Structure: Brick ☒ Wood Frame ☐ Stone ☐ Metal ☐
Other ☐

Surface Covering: Stucco ☐ Wood siding ☐ Other ☐

Roof Covering: Slate ☒ Metal ☐ Tile ☐ Asphalt ☐
Other ☐

Piazza: Foundation: Brick ☐ Stone ☐ Wood ☐
Other ☐

N/A Main Piazza: Brick ☐ Wood ☐ Other ☐

Roof Covering (if different from main building):

Chimneys: Brick ☐ Brick & Stucco ☒ Stone ☐ Other ☐

Comments:

Address:

Tax Map No.:

Page 2

Damage Assessment

None

Minor

Major

8

Exterior Features

Walls: Foundation/Basement	[]	[]	[]
1st Floor	[]	[]	[]
2nd Floor	[]	[]	[]
3rd Floor	[]	[]	[]
4th Floor	[]	[]	[]
Attic	[]	[]	[]
Doors	[]	[]	[]
Windows	[]	[]	[]
Shutters			
Piazza/Portico	[]	[]	[]
Downspouts	[]	[]	[]
Gutters	[]	[]	[]
Cornice	[]	[]	[]
Parapet	[]	[]	[]
Roof Covering	[]	[]	[]
Dormers (Number: 2)	[]	[]	[]
Chimneys (Number: 2)	[]	[]	[]

Other Visible Damage

Garden Walls/Fences	[]	[]	[]
Gates	[]	[]	[]
Walkways/Paving	[]	[]	[]
Sidewalks	[]	[]	[]
Trees	[]	[]	[]
Mechanical	[]	[]	[]