

Owner & Occupant	Material		Dimensions			Condition of Walls				Condition of Chimneys or Flues	\$ Damages by Earthquake
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West		
Miss Fowler, dwelling	Frame	Shingle	35	16	25	Good	Good	Good	Good	Rebuilt- now good	[none recorded]

What should be done to make it safe	Remarks
"O.K."	133 Cannon

Cite as: Record of Earthquake Damages, 1886. On microfiche, Historic Charleston Foundation Archives.