

15 Legare St.

Owner & Occupant	Material		Dimensions			Condition of Walls				Condition of Chimneys or Flues	\$ Damages by Earthquake
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West		
Mrs. S. Wragg, dwelling	Frame	Slate	45	22	40	Good	Good	Good	Good	Good	n/a
What should be done to make it safe	Remarks										
"O.K."											

Cite as: *Record of Earthquake Damages*, 1886. On microfiche, Historic Charleston Foundation Archives.