

Building	Material	Dimensions			Condition of Walls			Condition of Chimneys or Flues	Damages by Earthquake (\$)
		Roof	Ft. Long	Ft. Wide	Ft. High	North	South		
Church	Slate	60	20	35	6000				

18 Church St.

marks

HISTORIC CHARLESTON FOUNDATION
HURRICANE HUGO DAMAGE ASSESSMENT FORM

Date of Survey: 10-3-89

Video: Reel/Frame

Camera:

Slides: [2]

Survey Team: SOB
Members:

B.& W.: [2]

Name of Property: (if any)

Street Address: 18 CHURCH ST.

Tax Map Number: 457-16-4-48

Current Owner:

DESCRIPTION

Principal Building [] Dependency [] Other []

No. of Stories: Basement [] 1 [] 2 [] 3 [] 4 []

Attic or Half Story []

Material:

Structure: Brick [] Wood Frame [] Stone [] Metal []
Other []:

Surface Covering: Stucco [] Wood Siding [] Other []:

Roof Covering: Slate [] Metal [] Tile [] Asphalt []
Other []:

Piazza: Foundation: Brick [] Stone [] Wood []
Other []:

Main Piazza: Brick [] Wood [] Other []

Roof Covering (if different from main building):

Chimneys: Brick [] Brick & Stucco [] Stone [] Other []

Comments:

Damage Assessment	None	Minor	Major	%
-------------------	------	-------	-------	---

Exterior Features

Walls: Foundation/Basement	[<input checked="" type="checkbox"/>]	[<input type="checkbox"/>]	[<input type="checkbox"/>]	
1st Floor	[<input checked="" type="checkbox"/>]	[<input type="checkbox"/>]	[<input type="checkbox"/>]	
2nd Floor	[<input checked="" type="checkbox"/>]	[<input type="checkbox"/>]	[<input type="checkbox"/>]	
3rd Floor	[<input checked="" type="checkbox"/>]	[<input type="checkbox"/>]	[<input type="checkbox"/>]	
4th Floor	[<input type="checkbox"/>]	[<input type="checkbox"/>]	[<input type="checkbox"/>]	
Attic	[<input checked="" type="checkbox"/>]	[<input type="checkbox"/>]	[<input type="checkbox"/>]	
Doors	[<input checked="" type="checkbox"/>]	[<input type="checkbox"/>]	[<input type="checkbox"/>]	
Windows	[<input checked="" type="checkbox"/>]	[<input type="checkbox"/>]	[<input type="checkbox"/>]	
Shutters		[<input checked="" type="checkbox"/>]		10%
Piazza/Portico	[<input checked="" type="checkbox"/>]	[<input type="checkbox"/>]	[<input type="checkbox"/>]	
Downspouts	[<input checked="" type="checkbox"/>]	[<input checked="" type="checkbox"/>]	[<input type="checkbox"/>]	10%
Gutters	[<input type="checkbox"/>]	[<input checked="" type="checkbox"/>]	[<input type="checkbox"/>]	15%
Cornice	[<input checked="" type="checkbox"/>]	[<input type="checkbox"/>]	[<input type="checkbox"/>]	
Parapet	[<input type="checkbox"/>]	[<input type="checkbox"/>]	[<input type="checkbox"/>]	
Roof Covering	[<input type="checkbox"/>]	[<input checked="" type="checkbox"/>]	[<input type="checkbox"/>]	30%
Dormers (Number: 3)	[<input checked="" type="checkbox"/>]	[<input type="checkbox"/>]	[<input type="checkbox"/>]	
Chimneys (Number: 3)	[<input checked="" type="checkbox"/>]	[<input type="checkbox"/>]	[<input type="checkbox"/>]	

Other Visible Damage

Garden Walls/Fences	[<input checked="" type="checkbox"/>]	[<input type="checkbox"/>]	[<input type="checkbox"/>]
Gates	[<input checked="" type="checkbox"/>]	[<input type="checkbox"/>]	[<input type="checkbox"/>]
Walkways/Paving	[<input checked="" type="checkbox"/>]	[<input type="checkbox"/>]	[<input type="checkbox"/>]
Sidewalks	[<input checked="" type="checkbox"/>]	[<input type="checkbox"/>]	[<input type="checkbox"/>]
Trees	[<input checked="" type="checkbox"/>]	[<input type="checkbox"/>]	[<input type="checkbox"/>]
Mechanical	[<input type="checkbox"/>]	[<input type="checkbox"/>]	[<input type="checkbox"/>]

