

HISTORIC CHARLESTON FOUNDATION
HURRICANE HUGO DAMAGE ASSESSMENT FORM

Date of Survey:

Survey Team:
Members:

McCallum Lund
Kerley Rowe

Video: Reel/Frame

Camera:

Slides: [1]
B. & W.: []

Name of Property: (if any)

Street Address: 3 Henrietta

Tax Map Number: 459-13-3 lot 10

Current Owner:

DESCRIPTION

Principal Building ☒ Dependency ☐ Other ☐

No. of Stories: Basement [1] 1 ☐ 2 ☒ 3 ☐ 4 ☐
Attic or Half Story ☐

Material:

Structure: Brick ☐ Wood Frame ☒ Stone ☐ Metal ☐
Other ☐

Surface Covering: Stucco ☐ Wood Siding ☒ Other ☐

Roof Covering: Slate ☐ Metal ☒ Tile ☐ Asphalt ☐
Other ☐

Piazza: { Foundation: Brick ☐ Stone ☐ Wood ☐
Other ☐

W/A { Main Piazza: Brick ☐ Wood ☐ Other ☐

Roof Covering (if different from main building):

Chimneys: Brick ☒ Brick & Stucco ☐ Stone ☐ Other ☐

Comments:

[]
[]
Whole house leaning toward the right

Address: -

Tax Map No.:

Page 2

Damage Assessment

None

Minor

Major

\$

Exterior Features

Walls: Foundation/Basement	[]	[]	[X] <i>have coming off foundation</i>
1st Floor	[X]	[]	[]
2nd Floor	[X]	[]	[]
3rd Floor	N/A []	[]	[]
4th Floor	N/A []	[]	[]
Attic	[X]	[]	[]
Doors	[X]	[]	[]
Windows	[X]	[]	[]
Shutters	X		
Piazza/Portico	N/A []	[]	[]
Downspouts	[X]	[]	[]
Gutters	[]	[X]	[]
Cornice	[X]	[]	[]
Parapet	[X]	[]	[]
Roof Covering	[]	[]	[X] <i>50% damage</i>
Dormers (Number:)	[]	[]	[]
Chimneys (Number: 1)	[]	[X]	[] <i>bricks displace</i>

Other Visible Damage

Garden Walls/Fences	[]	[]	[]
Gates	[]	[]	[]
Walkways/Paving	[]	[]	[]
Sidewalks	N/A []	[]	[]
Trees	[]	[]	[]
Mechanical	[]	[]	[]

