

HISTORIC CHARLESTON FOUNDATION  
HURRICANE HUGO DAMAGE ASSESSMENT FORM

Date of Survey: 10-17

Survey Team: *CHARLESTON*  
Members: *Hendricks, Heck, Long (UF)*

Video: Reel/Frame

Camera:

Slides: [19, 20]

B. & W.: [26, 27]

*R. J.*

Name of Property: (if any) "German Friendly Society"

Street Address: 27 Archdale

Tax Map Number: 457-8-2-75

Current Owner:

DESCRIPTION

Principal Building  Dependency [ ] Other [ ]

No. of Stories: Basement [ ] 1 [ ] 2  3 [ ] 4 [ ]

Attic or Half Story [ ]

Material:

Structure: Brick [ ] Wood Frame  Stone [ ] Metal [ ]  
Other [ ]:

Surface Covering: Stucco [ ] Wood Siding  Other [ ]:

Roof Covering: Slate [ ] Metal  Tile [ ] Asphalt [ ]  
Other [ ]:

Piazza: Foundation: Brick  Stone [ ] Wood   
Other [ ]:

Main Piazza: Brick [ ] Wood  Other [ ]

Roof Covering (if different from main building):

Chimneys: Brick [ ] Brick & Stucco [ ] Stone [ ] Other [ ]

Comments:

NO VISIBLE DAMAGE TO HOUSE, ROOF HAS MINOR DAMAGE,  
HOWEVER, HOUSE SEEMS TO BE IN POOR CONDITION BECAUSE  
HUGO, i.e., PAINT PEELING, RUN DOWN APPEARANCE, etc.

Address: 27 Archdale

Tax Map No.: 457-8-2-75

Page 2

Damage Assessment	None	Minor	Major	%
-------------------	------	-------	-------	---

## Exterior Features

Walls: Foundation/Basement	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
1st Floor	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2nd Floor	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3rd Floor	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4th Floor	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Attic	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Doors	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Windows	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

## Shutters

Piazza/Portico	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Downspouts	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Gutters	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Cornice	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Parapet	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Roof Covering	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Dormers (Number: )	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Chimneys (Number: )	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

SOME MINOR DAMAGE

## Other Visible Damage

Garden Walls/Fences	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Gates	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Walkways/Paving	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Sidewalks	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Trees	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Mechanical	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

