

HISTORIC CHARLESTON FOUNDATION
HURRICANE HUGO DAMAGE ASSESSMENT FORM

Date of Survey: 11/14/89

Video: Reel/Frame

Camera:

Slides: []

B. & W.: []

Survey Team:

Members: Paul 2

Name of Property: (if any)

Street Address: 139 Ashley

Tax Map Number: 460-15-3-11

Current Owner:

DESCRIPTION

Principal Building ☒ Dependency ☐ Other ☐

No. of Stories: Basement ☐ 1 ☐ 2 ☒ 3 ☐ 4 ☐

Attic or Half Story ☐

Material:

Structure: Brick ☒ Wood Frame ☐ Stone ☐ Metal ☐
Other ☐

Surface Covering: Stucco ☒ Wood Siding ☐ Other ☐

Roof Covering: Slate ☐ Metal ☒ Tile ☐ Asphalt ☐
Other ☐: Flat

Piazza: Foundation: Brick ☐ Stone ☐ Wood ☐
Other ☐

Main Piazza: Brick ☐ Wood ☐ Other ☐

Roof Covering (if different from main building):

Chimneys: Brick ☒ Brick & Stucco ☐ Stone ☐ Other ☐

Comments:

Building has at least 5 major
pre storm cracks running from grade
to cornice. Looks inhabitable - could
have sustained major interior damage
to 2nd fl. ceiling.

Address:

Tax Map No.:

Page 2

Damage Assessment

None

Minor

Major

%

Exterior Features

Walls: Foundation/Basement [] [] []

1st Floor [] [X] [] 40 peeling

2nd Floor [] [X] [] 40 stucco

3rd Floor [] [] []

4th Floor [] [] []

Attic [] [] []

Doors [X] [] []

Windows [X] [] []

~~Shutters~~~~Piazza/Portico~~ [] [] []

Downspouts [X] [] []

Gutters [X] [] []

Cornice [X] [] []

Parapet [X] [] []

Roof Covering ? [] [] []

Dormers (Number: 0) [X] [] []

Chimneys (Number: 2) [X] [] []

Other Visible Damage

Garden Walls/Fences [X] [] []

Gates [X] [] []

Walkways/Paving [X] [] []

Sidewalks [X] [] []

Trees [X] [] []

Mechanical [X] [] []