

Owner & Occupant	Material		Dimensions			Condition of Walls				Condition of Chimneys or Flues	Damages by Earthquake (\$)	What should be done to make it safe	Remarks
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West				
1 Henrietta Henry Willie, Store	Frame	Tin	50	20	18	G	O	O	D	Rebuilt	\$10	"O.K."	[none recorded]

Cite as: *Record of Earthquake Damages, 1886*. On microfiche, Historic Charleston Foundation Archives