

Owner & Occupant	Material		Dimensions			Condition of Walls				Condition of Chimneys or Flues	Damages by Earthquake (\$)
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West		
S. Middleton	Frame	Shingle				Nothing recorded					→

What should be done to make it safe	Remarks
Old frame building beyond repairs; should be pulled down before it drops	Frame building in rear is in very good order.

3 Henrietta St.

Cite as: *Record of Earthquake Damages, 1886*. On microfiche, Historic Charleston Foundation Archives.