

Owner & Occupant	Material		Dimensions			Condition of Walls				Condition of Chimneys or Flues	Damages by Earthquake (\$)	What should be done to make it safe	Remarks
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West				
F.C. BORNER, DWELLING 32 George St.	Brick & Frame	Tin	40	30	50	← G	∅	○	D →	Good	[none assessed]	[nothing noted]	[no remarks]

Cite as: Record of Earthquake Damages, 1886. On microfiche, Historic Charleston Foundation Archives