

Owner & Occupant	Material		Dimensions			Condition of Walls				Condition of Chimneys or Flues	Damages by Earthquake (\$)
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West		
A. Moses, Vacant	Brick	Tin	45	22	35	Good	Good	Good	Good	Good	\$1200

What should be done to make it safe	Remarks
Now being repaired. O.K.	[none]

64 Beaufain

Cite as: Record of Earthquake Damages, 1886. On microfiche, Historic Charleston Foundation Archives.

Owner & Occupant	Material		Dimensions			Condition of Walls				Condition of Chimneys or Flues	Damages by Earthquake (\$)
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West		
— Thomas, Vacant	Brick	Tin	45	22	35	Cracked	Good	Good	Good	Good	[none recorded]

What should be done to make it safe	Remarks
Walls have been anchored. O.K.	[None]

66 Beaufain

Cite as: Record of Earthquake Damages, 1886. On microfiche, Historic Charleston Foundation Archives.

Owner & Occupant	Material		Dimensions			Condition of Walls				Condition of Chimneys or Flues	Damages by Earthquake (\$)
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West		
T. Finlay, Vacant	Brick	Tin	45	22	35	Top down	Top Down	Top Down	Top Down	Down - must be rebuilt	\$1250

What should be done to make it safe	Remarks
Veranda all down; rebuild top part of all walls and anchor them; repair all plastering	[none]

68 Beaufain

Cite as: Record of Earthquake Damages, 1886. On microfiche, Historic Charleston Foundation Archives.