

Owner & Occupant	Material		Dimensions			Condition of Walls				Condition of Chimneys or Flues	Damages by Earthquake (\$)
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West		
Carrington, Thomas & Company, Store and Office	Brick	Tin	100	22	35	Good	Good	Good	Good	First one very bad	—
What should be done to make it safe	Remarks										
OK except front chimneys; no fires should be made until it is fixed											

275 King St.

Cite as: Record of Earthquake Damages, 1886. On microfiche, Historic Charleston Foundation Archives.