

✓

HISTORIC CHARLESTON FOUNDATION
HURRICANE HUGO DAMAGE ASSESSMENT FORM

Date of Survey: 10-6-89

Video: Reel/Frame

Survey Team:

Camera:

Slides: [~~2~~ 4] Roll 6

Members: WILLIE GRAHAM, BOBBY KERR
KEN LYNCH, HUGH McALOON

B. & W.: [4] Roll 8

Name of Property: (if any)

Street Address: 101 Rutledge

Tax Map Number: 457-3-1--106

Current Owner:

DESCRIPTION

Principal Building ☒ Dependency ☐ Other ☐

No. of Stories: Basement ☒ 1 ☐ 2 ☒ 3 ☐ 4 ☐

Attic or Half Story ☒

Material:

Structure: Brick ☒ Wood Frame ☐ Stone ☐ Metal ☐
Other ☐:

Surface Covering: Stucco ☐ Wood Siding ☐ Other ☐:

Roof Covering: Slate ☒ Metal ☐ Tile ☐ Asphalt ☐
Other ☐:

Piazza: Foundation: Brick ☒ Stone ☐ Wood ☐
Other ☒: STUCCO

Main Piazza: Brick ☐ Wood ☒ Other ☐

Roof Covering (if different from main building):

Chimneys: Brick ☒ Brick & Stucco ☐ Stone ☐ Other ☐

Comments:

Address: 701 Rutledge

Tax Map No.: 457-3-1-100

Page 2

Damage Assessment	None	Minor	Major	%
-------------------	------	-------	-------	---

Exterior Features

Walls: Foundation/Basement	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
1st Floor	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
2nd Floor	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
3rd Floor	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
4th Floor	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Attic	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Doors	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Windows	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Shutters	<input checked="" type="checkbox"/>			
Piazza/Portico	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Downspouts	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Gutters	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Cornice	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Parapet	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Roof Covering	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	40%
Dormers (Number: 4)	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	window/roof
Chimneys (Number: 6)	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	1 damage to pot

Other Visible Damage

Garden Walls/Fences	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Gates	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Walkways/Paving	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Sidewalks	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Trees	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Mechanical	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

