

45 Pitt St.	Material		Dimensions			Condition of Walls				Condition of Chimneys or Flues	Damages by Earthquake (\$)	What should be done to make it safe	Remarks
Owner & Occupant	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West				
J. Ackerman, Dwelling	Frame	Tin	40	18	26	← G	○	○	D →	Down	\$70	Rebuild chimney from below roof line	n/a

Cite as: *Record of Earthquake Damages, 1886*. On microfiche, Historic Charleston Foundation Archives