

HISTORIC CHARLESTON FOUNDATION
HURRICANE HUGO DAMAGE ASSESSMENT FORM

Date of Survey: 10/18/89

Video: Reel/Frame

Camera:

Slides: [38] R#1
B. & W.: [33] R#3

Survey Team: HARLESTON

Members: D. Anderson
L. LEPETRIE

Name of Property: (if any)

Street Address: 45 PITT ST

Tax Map Number: 457-3-2-23

Current Owner:

DESCRIPTION

Principal Building Dependency [] Other []

No. of Stories: Basement [] 1 [] 2 3 [] 4 []

Attic or Half Story []

Material:

Structure: Brick [] Wood Frame Stone [] Metal []
Other []:

Surface Covering: Stucco [] Wood Siding Other []:

Roof Covering: Slate [] Metal Tile [] Asphalt []
Other []:

Piazza: Foundation: Brick Stone [] Wood []
Other : MASONRY

Main Piazza: Brick [] Wood Other []

Roof Covering (if different from main building):

Chimneys: Brick Brick & Stucco [] Stone [] Other []

Comments:

Address:

Tax Map No.:

Page 2

Damage Assessment None Minor Major %

Exterior Features

Walls: Foundation/Basement	[✓]	[]	[]
1st Floor	[✓]	[]	[]
2nd Floor	[✓]	[]	[]
3rd Floor	[✓]	[]	[]
4th Floor	[✓]	[]	[]
Attic	[✓]	[]	[]
Doors	[✓]	[]	[]
Windows	[]	[X]	[]

Shutters

Piazza/Portico	[✓]	[]	[]
Downspouts	[✓]	[]	[]
Gutters	[]	[X]	[]
Cornice	[✓]	[]	[]
Parapet	[✓]	[]	[]
Roof Covering	[✓]	[]	[]
Dormers (Number:)	[✓]	[]	[]
Chimneys (Number: 3)	[✓]	[]	[]

Other Visible Damage

Garden Walls/Fences	[]	[X] <i>Possibly</i> []	
Gates	[✓]	[]	[]
Walkways/Paving	[✓]	[]	[]
Sidewalks	[✓]	[]	[]
Trees	[✓]	[]	[]
Mechanical	[✓]	[]	[]

