

140 Broad St.

Owner & Occupant	Material		Dimensions			Condition of Walls				Condition of Chimneys or Flues	\$ Damages by Earthquake	
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West			
Dr. W.H. Huger, dwelling	Frame	Slate	50	50	30	Good	Good	Good	Good	[not recorded]	[no \$ recorded]	
What should be done to make it safe	Remarks											
Now being rebuilt.	[none recorded]											

Cite as: *Record of Earthquake Damages*, 1886. On microfiche, Historic Charleston Foundation Archives.