

HISTORIC CHARLESTON FOUNDATION
HURRICANE HUGO DAMAGE ASSESSMENT FORM

Date of Survey: 10-17-89

Video: Reel/Frame

Camera:

Survey Team: CLEMSON
Members:

Slides: []

B. & W.: []

Name of Property: (if any) AME CHURCH

Street Address: 110 ~~100~~ CALHOUN ~~110~~

Tax Map Number: 459-13-3 17

Current Owner:

DESCRIPTION

Principal Building [☒] Dependency [] Other []

No. of Stories: Basement [☒] 1 [☒] 2 [] 3 [] 4 []

Attic or Half Story [] w/ GALLERY

Material:

Structure: Brick [☒] Wood Frame [] Stone [] Metal []
Other []:

Surface Covering: Stucco [☒] Wood Siding [] Other []:

Roof Covering: Slate [] Metal [] Tile [] Asphalt [☒]
Other []:

Piazza: Foundation: Brick [] Stone [] Wood []
Other []:

Main Piazza: Brick [] Wood [] Other []

Roof Covering (if different from main building):

Chimneys: Brick [] Brick & Stucco [] Stone [] Other []

Comments: TOWER MISSING TOP

Address:

Tax Map No.:

Page 2

Damage Assessment

None

Minor

Major

%

Exterior Features

Walls: Foundation/Basement

☒☐☐

1st Floor

☒☐☐

2nd Floor

☐☐☐

3rd Floor

☐☐☐

4th Floor

☐☐☐

Attic

☐☐☐

Doors

☒☐☐

Windows

☐☒☐

10 %

Shutters

Piazza/Portico

☐☐☐

Downspouts

☒☐☐

Gutters

☒☐☐

Cornice

☒☐☐

Parapet

☐☐☐

Roof Covering

☐☒☐

5 %

Dormers (Number: 0)

☐☐☐

Chimneys (Number: 0)

☐☐☐

Other Visible Damage

Garden Walls/Fences

☐☒☐

15 %

Gates

☐☒☐

10 %

Walkways/Paving

☒☐☐

Sidewalks

☒☐☐

- Trees

☐☒☐

5 %

Mechanical

☒☐☐







