

Owner & Occupant	Material		Dimensions			Condition of Walls				Condition of Chimneys or Flues	Damages by Earthquake (\$)	What should be done to make it safe	Remarks
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West				
9 Glebe Mrs. Blank, dwelling	Brick	Tin	40	18	30	Good	Good	Down	Cracked	Down	775	East & west walls are being taken down and rebuilt from ground. Rebuild chimneys from below ceiling joists & anchor walls.	N/A

Cite as: Record of Earthquake Damages, 1886. On microfiche, Historic Charleston Foundation Archives

HISTORIC CHARLESTON FOUNDATION
HURRICANE HUGO DAMAGE ASSESSMENT FORM

Date of Survey: 10.18.89

Video: Reel/Frame

Camera:

Slides: [25]

R-2

Survey Team: Rosenthal Sch
Members: 14 CHARLESTON

B. & W.: [25]

R-2

Name of Property: (if any)

Street Address: 9 GLEBE

Tax Map Number: 457-4-27

Current Owner:

DESCRIPTION

Principal Building Dependency [] Other []

No. of Stories: Basement [] 1 [] 2 3 [] 4 []

Attic or Half Story

Material:

Structure: Brick [] Wood Frame [] Stone [] Metal []
Other : STUCCO *AND STONE*

Surface Covering: Stucco Wood Siding [] Other []:

Roof Covering: Slate [] Metal Tile [] Asphalt []
Other []:

Piazza: Foundation: Brick [] Stone [] Wood []
Other []: STUCCO *AND STONE*

Main Piazza: Brick [] Wood Other []

Roof Covering (if different from main building):

Chimneys: Brick [] Brick & Stucco [] Stone [] Other []

None

Comments:

Address:

Tax Map No.:

Page 2

Damage Assessment None Minor Major %

Exterior Features

Walls: Foundation/Basement	[X]	[]	[]
1st Floor	[X]	[]	[]
2nd Floor	[X]	[]	[]
3rd Floor	[X]	[]	[]
4th Floor	[X]	[]	[]
Attic	[X]	[]	[]
Doors	[X]	[]	[]
Windows	[X]	[]	[]

Shutters

Piazza/Portico	[X]	[]	[]
Downspouts	[]	[X]	[]
Gutters	[]	[X]	[]
Cornice	[X]	[]	[]
Parapet	[X]	[]	[]
Roof Covering	[]	[X]	[]
Dormers (Number: 7)	[X]	[]	[]
Chimneys (Number: 2)	[X]	[]	[]

Other Visible Damage

Garden Walls/Fences	[X]	[]	[]
Gates	[X]	[]	[]
Walkways/Paving	[X]	[]	[]
Sidewalks	[X]	[]	[]
Trees	[X]	[]	[]
Mechanical	[]	[]	[]

