

48 SOCIETY ST.

Owner & Occupant	Material		Dimensions			Condition of Walls				Condition of Chimneys or Flues	\$ Damages by Earthquake
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West		
G. VAN OHSEN, BAKERY & DWELLING	BRICK	TIN	35	35	25	GOOD	CRACKED OVER OPENINGS	SLIGHTLY CRACKED	SLIGHTLY CRACKED	GOOD	\$150

What should be done to make it safe	Remarks
ANCHOR BUILDING FROM EAST TO WEST	N/A

Cite as: *Record of Earthquake Damages*, 1886. On microfiche, Historic Charleston Foundation Archives.