

HISTORIC CHARLESTON FOUNDATION
HURRICANE HUGO DAMAGE ASSESSMENT FORM

Date of Survey:

Video: Reel/Frame

Survey Team:

Camera:

Members:

Slides: []

B. & W.: []

Name of Property: (if any)

Street Address: *418 South*

Tax Map Number: *458-1-3-39*

Current Owner:

DESCRIPTION

Principal Building [☒] Dependency [] Other []

No. of Stories: Basement [] 1 [] 2 [☒] 3 [] 4 []

Attic or Half Story []

Material:

Structure: Brick [☒] Wood Frame [] Stone [] Metal []
Other []:

Surface Covering: Stucco [☒] Wood Siding [] Other []:

Roof Covering: Slate [] Metal [] Tile [] Asphalt []
Other []: *Flat*

Piazza: Foundation: Brick [☒] Stone [] Wood []
Other []:

Main Piazza: Brick [] Wood [☒] Other []

Roof Covering (if different from main building):

Chimneys: Brick [☒] Brick & Stucco [] Stone [] Other []

Comments:

Address:

Tax Map No.:

Page 2

Damage Assessment

None

Minor

Major

%

Exterior Features

Walls: Foundation/Basement

[] [] []

1st Floor

[✓] [] []

2nd Floor

[✓] [] []

3rd Floor

[] [] []

4th Floor

[] [] []

Attic

[] [] []

Doors

[✓] [] []

Windows

[] [✓] [] 20%

Shutters

[] [✓] [] 100%

Piazza/Portico

[✓] [] []

Downspouts

[✓] [] []

Gutters

[✓] [] []

Cornice

[✓] [] []

Parapet

[✓] [] []

Roof Covering

[] [✓] []

Dormers (Number:)

[✓] [] []

Chimneys (Number:)

[] [✓] []

Other Visible Damage

Garden Walls/Fences

[✓] [] []

Gates

[✓] [] []

Walkways/Paving

[✓] [] []

Sidewalks

[✓] [] []

Trees

[✓] [] []

Mechanical

[✓] [] []