






REFLECTED CEILING PLAN

EAST ELEVATION
BREAKFAST ROOM



EAST ELEVATION - ELEVATION



EAST ELEVATION HORIZON




EAST ELEVATION




EAST ELEVATION & CEILING (PARTIAL)


NORTH ELEVATION
BREAKFAST ROOM




NORTH ELEVATION - ELEVATION




NORTH ELEVATION - PHOTO




WEST ELEVATION - ELEVATION




WEST ELEVATION - PHOTOGRAPH



SOUTH ELEVATION - ELEVATION




SOUTH ELEVATION - ELEVATION




East elevation: note fragments of original blue and white-yellow over paint at horizon. Note crazing of mural paint layer.



West elevation: note poor condition of mural surface at select areas of sky/ horizon. Photo digitally enhanced.




Northwest vault: note peeling/ flaking paint at sky/ horizon.



South elevation: detail of horizon. Note poor condition of mural surface at select areas of sky/ horizon. Photo digitally enhanced.



Ceiling: note large areas of peeling paint, different paint sheens and old repairs.



West elevation: note patches of rough surface texture including peeling paint.




Over-paint removal test. Horizon-sky junction. Photo digitally enhanced.

Latex paint removal test. Latex is the white/yellow/beige paint layer.

Original paint under latex - base layer. Additional paint layers added over base layer to create final appearance.

Paint strokes visible under latex paint. Paint color is lighter than base color.

Note build up of paint layers. Top layer is very thin.



Over-paint removal test. Horizon-sky junction. Photo digitally enhanced.

Latex paint removal test. Latex is the white/yellow/beige paint layer. Thickness of latex paint varies.