



A black and white photograph showing a close-up of an aircraft's fuselage. A rectangular panel is labeled "MASTER REFUELLING DOOR". The surrounding skin is heavily damaged, with large areas of paint or material missing, revealing a rough, fibrous texture underneath. A vertical seam or crack runs down the right side of the panel. The overall appearance is one of significant wear and tear.

MASTER
REFUELLING
DOOR