







Samuel L. Allen, Section E, Lot 018, fallen coping on
north side, 8-3-2004



Samuel L. Allen, misalignment of coping
on west side, 8-3-2004








**NEWSOM
C-072 NW 1/4
March 14, 2005**

**Corner post is lying on ground. No similar corners nearby.
Where does it belong? Or the other corners sunken?**

**W 1/2 was purchased by S. H. McElroy 1883.
NW 1/4 transferred to Newsom.
E 1/2 purchased by Sallie C. Waties 1880.**





Done



Dormant

HS - 170


798

96 - No Contact



HS-170 (see above right)

Done




C-072

E 1/2 - # 3222 Last buried 1913

NW 1/4 - # 2255 Last buried 1893

SW 1/4 - # 2026 Last buried 1909


all 80 (no DOP) also no



E-095 see above

(shows previous attempt to repair.)

Marie is wife of Michael, a native of Paris, France and Houston's first "real" architect. He's also buried on E-095.



E-135 ?

Wilson # 3362 + 3683
96 - no contact

Piece of stone has been sitting there a long time. May be piece of coping or corner post from another lot.



E-002 ?

A. Connell #581

80 - no DOP
no contact


Last burial 1968

Done




E-002 see left

Done




← E-067 →
Lobdell
E-067
80 - no DOP
no contact.

Cradle pieces
buried or
missing.




E-065 →




E-065
Roberts # 2605
80 - no DOP
no contact
Last burial 1932


See copying
on next
page



E-065 see above
coping broken, sunken.
marker? (washed)




E-065 see left + above.





C-155.5
McGlasson-
Birch

Butler light
(12:15 P.)
copies
material?




Section West Avenue, Lot 278 (Cranford)
Looking west from road
Crumbled and missing coping; stucco over granite
rubble with reinforcing rods






Section C, Lots 152, 153, 154, 188 (House)
Looking southeast from road
Granite posts in coping tilted, pipe rails fallen



Section C, Lots 152, 153, 154, 188 (House)
Looking east from road
Granite posts in coping tilted, pipe rails fallen


**DORSEY
C-004**

Repair broken vase only to prevent piece from being lost




**DORSEY
C-004**

Repair broken vase only to prevent piece from being lost



Lloyd
C-024



Dormant
HS-170

Done



DeChaumes
E-095



Stone



Wilson
E-135



Railey
EA-045



Gabel
C-026



Henderson
WA-354



Kidd
WA-301



Cushman
E-048

