

SCHEDULE OF PHOTOGRAPHY

- 1 Landscape from hilltop south of campus, view is due north.
- 2 Camera positioned directly above structure of root cellar looking north
- 3 View to northwest from cemetery, stone markers are in mid foreground; chicken coops (c) left of center
- 4 West facing elevation original 1874/80 center building (c). White painted masonry evidences area of covered porches recently demolished.
- 5 Center section photo shows history of alterations. **NOTE: Photographer was not allowed access to "The Yard" during more optimal photographic times of natural sunlight washing of the façade**
- 6 View is looking southwest from the roof of the "Park" building toward the back of the four-story center building, 3-story wings and power plant building

Photos 7 through 16 show distribution of detail of polychromatic brick/stone work typical of "Venetian Gothic"

- 7 View to north, center administration building. Columned and pointed arches, horizontal limestone coursing, windows bricked in.
- 8 View north as above. Center build, original walls remained after fire of 1879. All original openings filled in. Only center structure has 4th floor.
- 9 Close up of masonry elements at west facing front entry shows:
 - a. Red brick made on site
 - b. Milwaukee brick (white trim)
 - c. Carved limestone from Andrew County Quarry. See photo #10.
- 10 See photo #5 before stripping of "porch" point. Brick/stone work polychromy degraded.
- 11 Dormer shown, same as that of photo #8 south elevation. This photo was taken to illustrate the design consistency of the original polychromy. **NOTE: The applied ornament of the dormer verge board and linear moldings. They recall the brickwork patterning of the column arches, and were originally polychrome painted to match the masonry arches.** See 1874 photo, opposite page.
- 12 Reference above.
- 13 Bays at north and south wings were added with the 1886 renovations.
- 14 West facing center building. Photo taken December 2002; three months after photo #5.
- 15 Encaustic floor tile installed 1903 throughout hallway floors; photos 17 and 19 show other patterns.
- 16 Photo is of middle of north wing showing bays added in 1893 minus polychromy.

- 17-18 Interior photography was very limited. Photo shows interior of bay pictures in photo 16. Almost no surfaces are as original. Floor is terrazzo, walls are fired out and sheet rocked, tracery follows original.
- 19 See comment 15.
- 20 Photo is taken from roof of the park building looking northeast at the rear of the Woodson Building. (c)
- 21 South view of Woodson Building entrance
- 22 Entry of Woodson Building; 1937 shows beautiful "Art Modern" limestone carved decoration, accents, remove, recall limestone coursing of 1874 high Victorian center build.
- 23 View is southwest showing juncture of the clinic building, 1923 (c), on left and the Glore Museum, 1969 (nc) on right.
- 24 Rear of clinic building, north view from park building roof
- 25 Again, from park roof looking south-southwest. This view conveys a sense of functional relationships and how resources were interrelated. Also, how adaptive reuse structures such as security fencing/alters feeling and association.
- 26 Landscape view looking north demonstrates how district has retained its rural setting.
- 27 New looking west of the original employee dormitory now "Regional Offices" building, 1935 (c). One of three W;P.A. building projects. See also #47 close up of entry. Neo-classical elements again recall polychromy of original administration building.
- 28 Rear of same three-story building, looking east.
- 29 Buchanan Building, 1949 (c). Three-story brick and limestone with crenelated parapet.
- 30 Side view of above looking east.
- 31 Landry Building-Original section on right, constructed 1933, W.P.A. addition on left (north), 1938. View is northeast.
- 32 Maintenance shop, 1931 (c). View is southwest.
- 33 Brick and frame greenhouse (2) buildings, brick structure on right is believed to be 1880s bathhouse. View is to west.
- 34 #45 originally outpatient facility now education/warehouse, 1957, (nc). View is east.
- 35 Old "Sheltered Workshop" now maintenance building, 1909 (c). Two-story brick with basement view is south.
- 36 Rear of same view is northeast.
- 37 "Progress Hall", 1893, addition 1940 (Brick building to be demolished as funds permit). See also photos 48/49. View is east.
- 38 Park building, 1936, (c). Five-story with basement, currently inmate housing. View is to the west. See #50, roof of park
- 39 View looking north from south end of cemetery site, note simple stone markers.
- 40-41 One of five (5) 1950 (c) "Minimal Traditional" brick "Doctors Homes."
- 42 Superintendent's house, 1860. No records exist documenting physical alterations, (c) architects, etc. See digital photos #57, 58 and 59. Two-story with basement. Photo 42 looking north, building front falls south to Fredrick Street.

- 43 Maintenance shop, 1899, (c), still in use, wood frame construction on brick/stone foundation. (Old Carriage House)
- 44 Root Cellar 1937 (c)
- 45 "Outpatient Building" same as #34, (35MM)
- 46 "Buchanan Building", same as #29, (35 MM)
- 47 "Employee Dorm", same as #27, (35 MM)
- 48-49 "Progress Hall", photo #37, (35 M)
- 50 Park Building Roof", view looking southwest
- 51 "Woodson Building", streetscape
- 52 View looking northwest from cemetery site. Years ago, DMH removed grave markers for better mowing. 1910 Poultry Shed is left center, new western "Reception & Diagnostic Center." Old Center Administrative Building is at far right. Photo illustrates invasiveness of security fencing.
- 53 View is east from backyard of doctor cottage in photo #40. Structures such as fencing, lighting, security, sidewalks, etc, have created "adverse effects."
- 54 Entrance to new Reception and Diagnostic Center.
- 55 One of few tombstones showing name
- 56 1860 superintendent's house (c) with garage, 10 ac., facing façade. House and adjacent barn/garage with formal english garden is visible at upper left of 1935 aerial photo. See attached.

Digital photos 57-60

- 57 Back of house looking southeast
- 58 West side, view to east
- 59 Same as #39 looking west. Basement is 4-course brick on stone/concrete foundation. Upper two stories are stucco on wood finish that has existed more than 30 years. Roof overhang, style of windows and doors suggest last renovation dates to "Prairie Style" of 1910-20.
- 60 View of Old Carriage House (c) 1899. Brick/stone foundation, upper story and half, is stucco on wood framing, same as house.