Architectural Survey of 17 - 44 Fraleigh Street Red Hook, New York

prepared by: Brent Kovalchik, R.A. 18 Fraleigh Street

Mark Burns

Mark Burns 40 Fraleigh Street September 28, 1992 September 10, 1992 Members of the Red Hook Zoning Board,

The following is an architectural survey of the houses on the portion of Fraleigh Street between Church and Phillips Streets.

The survey lists features of each house objectively and is absent of any interpretive stylistic concerns. The categories of the survey include: number of floors above grade; set back from the center line of the street; roof pitch; roof and siding materials; type, proportion, orientation, quantity and trim of windows; and other features of each house such as dormers and garages. These features are then used as the basis for determining the architectural character of the Fraleigh Street Neighborhood. It is with these characteristics and features that guidelines are proposed to aid in the determination of deed restrictions for the recently subdivided properties at 33-39 Fraleigh Street.

The results of this survey, along with the proposed guidelines, are listed following the survey. These guidelines are not intended to deter the sale of or prohibit new construction on these properties. They are offered as useful factors that ought to be considered in order to maintain the rural, small town characteristics of Fraleigh Street.

PROPOSED GUIDELINES

PROPOSED GUIDELINES

OF FLOORS ABOVE GRADE: 2

SET BACK FROM CTR LINE OF STREET: Porch: 30' 0" - 35' 0" (based on existing properties House: 35' 0" - 45' 0" on North side of Fraleigh St)

CONSTRUCTION TYPE: Wood frame on masonry foundation (trim & accessories excluded) No masonry, concrete, fiberglass, steel, etc.

FRONT PORCH: Optional, but desirable

LOCATION OF PRIMARY ENTRANCE: Street facade (North side/South facade)

GARAGE/Out Buildings: Detached: not connected to main part of structure

DOORS/WINDOWS PER FLOOR: 2 - 3

WINDOW TYPE: double hung/casement

with not less than 3:5 (vertical/horizontal)

not greater than 2:1 (vert/horiz) proportion

WINDOW SPACING: 2nd flr windows to align w/lst flr windows & doors

WINDOW ORIENTATION:

1st flr: vertical

2nd flr: vertical or, if horizontal, width not to exceed those centered below on first floor

WINDOW TRIM AND SIZE: 4" - 5" jambs w/ corresponding heads either molded or similar to jamb trim

DORMERS: Not desirable

SIDING MATERIAL: Horizontal siding

of wood, aluminum, asbestos composite, shingle or wood shingle

ROOF PITCH: Not less than 7:12, No greater than 12:12

ROOF MATERIAL: Standing seam metal or asphalt shingles

ROOF TYPE: Gable

GABLE & EAVE TRIM: Desirable to have fascia with cornice expression of same material

START OF EAVE OR ROOF LINE: Above 2nd flr window heads

SET BACK FROM

CTR LINE OF STREET: Porch: 44' 0"

House: 52' 0"

CONSTRUCTION TYPE: Wood frame on

masonry foundation

FRONT PORCH: Yes - raised

LOCATION OF PRIMARY ENTRANCE:

North facade/Street facade START OF EAVE:

GARAGE: Detached

ROOF PITCH: 12:12

ROOF MATERIAL:

Asphalt shingles

w/Tin

ROOF TYPE: Gable and

hip

GABLE & EAVE TRIM:

fascia with molded

cornice

Above 2nd flr window heads

DOORS/WINDOWS

PER FLOOR: 1st flr: 3

2nd flr: 2

WINDOW TYPE: 1st flr: double-hung

2nd flr: double-hung

PROPORTION

OF WINDOWS: (Vertical: Horizontal)

1st flr - 2:1

2nd flr - 2:1

WINDOW SPACING: a:b:a:b:a:b:a

2nd flr windows aligned

w/lst flr windows

WINDOW ORIENTATION:

1st flr: vertical

2nd flr: vertical

WINDOW TRIM AND SIZE:

5" jamb trim

with molded head

DORMERS: No

SIDING MATERIAL:

horizontal asbestos

composite shingles



SET BACK FROM

CTR LINE OF STREET: Porch: 43' 0"

House: 52' 0"

CONSTRUCTION TYPE: Wood frame on

masonry foundation

FRONT PORCH: Yes - raised

LOCATION OF PRIMARY ENTRANCE:

North facade/Street facade

GARAGE: Detached

DOORS/WINDOWS

PER FLOOR: 1st flr: 3

2nd flr: 2

WINDOW TYPE: 1st flr: double-hung

2nd flr: double-hung

and double-hung

combination

PROPORTION

OF WINDOWS: (Vertical: Horizontal)

1st flr - 2:1 2nd flr - 2:1

WINDOW SPACING:

1st and 2nd flr windows

not aligned

WINDOW ORIENTATION:

lst flr: vertical
2nd flr: vertical

WINDOW TRIM AND SIZE:

4" jamb w/crossetts and

molded head

DORMERS: No

SIDING MATERIAL: horizontal wood

and aluminum

siding

ROOF PITCH: 8:12

ROOF MATERIAL:

Asphalt shingles/ rubber membrane on

tin

ROOF TYPE: Gable, open

on E/W & N/S axis

GABLE & EAVE TRIM:

fascia with fret work and molded

cornice

START OF EAVE:

Above 2nd flr



SET BACK FROM CTR LINE OF STREET: House: 25' 0"

CONSTRUCTION TYPE: Wood frame on masonry foundation

FRONT PORCH: No

LOCATION OF PRIMARY ENTRANCE: East facade

GARAGE: No

DOORS/WINDOWS
PER FLOOR: 2

WINDOW TYPE: double-hung

PROPORTION

OF WINDOWS: (Vertical:Horizontal)
5:3

WINDOW SPACING: a:b:c:b:a

WINDOW ORIENTATION: vertical

WINDOW TRIM AND SIZE:
5" jamb w/ head trim

DORMERS: No

SIDING MATERIAL:

horizontal asbestos composite shingle

ROOF PITCH: 8:12

ROOF MATERIAL:
Asphalt shingles

ROOF TYPE: Gable, open on North/South axis

GABLE & EAVE TRIM: metal flashing & drip

START OF EAVE:
Above 1st flr
window heads



SET BACK FROM

CTR LINE OF STREET: Porch: 34' 0"

House: 38' 0"

CONSTRUCTION TYPE: Wood frame on

masonry foundation

FRONT PORCH: Yes

LOCATION OF PRIMARY ENTRANCE:

North facade/Street facade

GARAGE: Detached

DOORS/WINDOWS

PER FLOOR: 1st flr: 3

2nd flr: 3

WINDOW TYPE: 1st flr: double-hung

2nd flr: awning

PROPORTION

OF WINDOWS: (Vertical: Horizontal)

1st flr - 3:2 2nd flr - 1:2

WINDOW SPACING: a:b:a:b:a:b:a

2nd flr windows aligned

w/lst flr windows

WINDOW ORIENTATION:

lst flr: vertical
2nd flr: horizontal

WINDOW TRIM AND SIZE:

5" jamb & head trim

DORMERS: No

SIDING MATERIAL:

wood horizontal siding

ROOF PITCH: 7:12

ROOF MATERIAL: Tin

ROOF TYPE: Gable, open

on East/West axis

GABLE & EAVE TRIM:

Decorative porch brackets w/fascia

and molded cornice

START OF EAVE:

Above 2nd flr window heads



SET BACK FROM

CTR LINE OF STREET: Porch: 47' 0"

House: 54' 0"

CONSTRUCTION TYPE: Wood frame on

masonry foundation

FRONT PORCH: Yes

LOCATION OF PRIMARY ENTRANCE:
North facade/Street facade

GARAGE: Detached

DOORS/WINDOWS PER FLOOR:

1st flr: 3 on primary form 2nd flr: 3 on primary form

WINDOW TYPE: 1st flr: double-hung

2nd flr: double-hung

PROPORTION

OF WINDOWS: (Vertical: Horizontal)

lst flr - 2:1 2nd flr - 2:1

WINDOW SPACING: a:b:a:b:a:b:a

2nd flr windows aligned

w/lst flr windows

WINDOW ORIENTATION:

lst flr: vertical
2nd flr: vertical

WINDOW TRIM AND SIZE:

5" trim w/molded heads

- shutters

DORMERS: No

SIDING MATERIAL:

horizontal wood

siding

ROOF PITCH: 7:12

ROOF MATERIAL:

Asphalt shingles

ROOF TYPE: Gable, open

on East/West & North/South axis

GABLE & EAVE TRIM: fascia and molded

START OF EAVE:
Above 2nd flr

cornice

window



36 FRALEIGH STREET

OF FLOORS ABOVE GRADE: 2

SET BACK FROM

CTR LINE OF STREET: Porch: 47' 0"

House: 53' 0"

CONSTRUCTION TYPE: Wood frame on

masonry foundation

FRONT PORCH: Yes - raised

LOCATION OF PRIMARY ENTRANCE:

North facade/Street facade

GARAGE: Detached

DOORS/WINDOWS

PER FLOOR:

1st flr: 3

2nd flr: 3

WINDOW TYPE: 1st flr: double-hung

2nd flr: double-hung

PROPORTION

OF WINDOWS: (Vertical: Horizontal)

1st flr - 2:1 2nd flr - 2:1

WINDOW SPACING: a:b:a:b:a:b:a

2nd flr windows aligned

w/lst flr windows

WINDOW ORIENTATION:

1st flr: vertical

2nd flr: vertical

WINDOW TRIM AND SIZE:

4" jambs w/molded heads

- shutters

DORMERS: No

SIDING MATERIAL:

horizontal wood

siding

ROOF PITCH: 7:12

ROOF MATERIAL:

Asphalt shingles

ROOF TYPE: Gable, open

on East/West axis

GABLE & EAVE TRIM:

fascia w/ bracketed

molded cornice

START OF EAVE:

Above 2nd flr



SET BACK FROM

CTR LINE OF STREET: Porch: 44' 0"

House: 49' 0"

CONSTRUCTION TYPE: Wood frame on

masonry foundation

FRONT PORCH: Yes - raised

LOCATION OF PRIMARY ENTRANCE:

North facade/Street facade

GARAGE: No

DOORS/WINDOWS

PER FLOOR: 1st flr: 3

2nd flr: 2

WINDOW TYPE: 1st flr: double-hung

2nd flr: double-hung

PROPORTION

OF WINDOWS: (Vertical: Horizontal)

1st flr - 2:1

2nd flr - 2:1

WINDOW SPACING: a:b:a:b:a:b:a

2nd flr windows aligned

w/lst flr windows

WINDOW ORIENTATION:

1st flr: vertical

2nd flr: vertical

WINDOW TRIM AND SIZE:

5" jambs w/ molded head

- shutters

DORMERS: No

SIDING MATERIAL:

horizontal wood

siding

ROOF PITCH: 8:12

ROOF MATERIAL:

Asphalt shingles

ROOF TYPE: Gable - open

on North/South axis

GABLE & EAVE TRIM:

fascia with molded

cornice

START OF EAVE:

Above 2nd flr



SET BACK FROM

CTR LINE OF STREET: Porch: 35' 0"

House: 40' 0"

CONSTRUCTION TYPE: Wood frame on

masonry foundation

FRONT PORCH: Yes - raised

LOCATION OF PRIMARY ENTRANCE:

North facade/Street facade

GARAGE: Detached

DOORS/WINDOWS

1st flr: 3 PER FLOOR:

2nd flr: 3

WINDOW TYPE: 1st flr: double-hung

2nd flr: double-hung

PROPORTION

OF WINDOWS: (Vertical: Horizontal)

1st flr - 2:1 2nd flr - 3:2

WINDOW SPACING: a:b:a:b:a:b:a

2nd flr windows aligned

w/lst flr windows

WINDOW ORIENTATION:

1st flr: vertical

2nd flr: vertical

WINDOW TRIM AND SIZE:

1" jamb & head trim

DORMERS: No

SIDING MATERIAL:

aluminum horizontal

siding

ROOF PITCH: 8:12

ROOF MATERIAL: Tin

ROOF TYPE: Gable, open

on East/West and North/South axis

GABLE & EAVE TRIM:

covered

START OF EAVE:

Above 2nd flr window heads



SET BACK FROM

CTR LINE OF STREET: Porch: 29' 0"

House: 34' 0"

Wood frame on CONSTRUCTION TYPE:

masonry foundation

FRONT PORCH: Yes - raised

LOCATION OF PRIMARY ENTRANCE:

South facade/Street facade

GARAGE: No

DOORS/WINDOWS

PER FLOOR: 1st flr: 3

2nd flr: 3

WINDOW TYPE: 1st flr: double-hung

2nd flr: double-hung

PROPORTION

OF WINDOWS: (Vertical: Horizontal)

1st flr - 3:2 2nd flr - 3:2

WINDOW SPACING: a:b:a:b:a:b:a

2nd flr windows aligned

w/lst flr windows

WINDOW ORIENTATION:

lst flr: vertical
2nd flr: vertical

WINDOW TRIM AND SIZE:

5" trim & head trim

DORMERS: No

SIDING MATERIAL:

horizontal asbestos composite siding

ROOF PITCH: 7:12

ROOF MATERIAL:

Asphalt shingles

ROOF TYPE: Gable, open

on North/South axis

GABLE & EAVE TRIM:

fascia with molded

cornice

START OF EAVE:

Above 2nd flr



23 FRALEIGH STREET (North Side)

OF FLOORS ABOVE GRADE: 2

SET BACK FROM

CTR LINE OF STREET: Porch: 27' 0"

House: 33' 0"

CONSTRUCTION TYPE: Wood frame on

masonry foundation

FRONT PORCH: Yes - raised

LOCATION OF PRIMARY ENTRANCE:

South facade/Street facade

GARAGE: Detached

DOORS/WINDOWS

PER FLOOR: 1st flr: 3

2nd flr: 3

WINDOW TYPE: 1st flr: double-hung

2nd flr: awning

PROPORTION

OF WINDOWS: (Vertical: Horizontal)

1st flr - 2:1 2nd flr - 1:2

WINDOW SPACING: a:b:a:b:a:b:a

2nd flr windows aligned

w/lst flr windows

WINDOW ORIENTATION:

1st flr: vertical 2nd flr: horizontal

WINDOW TRIM AND SIZE:

5" jamb and head trim

DORMERS: No

SIDING MATERIAL:

horizontal asbestos composite shingles

ROOF PITCH: 7:12

ROOF MATERIAL: Tin

ROOF TYPE: Gable, open

on East/West axis

GABLE & EAVE TRIM:

fascia with molded

cornice

START OF EAVE:

Above 2nd flr



SET BACK FROM

CTR LINE OF STREET: Porch: 39' 0"

House: 44' 0"

CONSTRUCTION TYPE: Wood frame on

masonry foundation

FRONT PORCH: Yes - raised

LOCATION OF PRIMARY ENTRANCE:

South facade/Street facade

GARAGE: Detached

DOORS/WINDOWS

PER FLOOR:

1st flr: 5 2nd flr: 4

WINDOW TYPE: 1st flr: double-hung

2nd flr: double-hung

PROPORTION

OF WINDOWS: (Vertical: Horizontal)

1st flr - 3:2

2nd flr - 3:2

WINDOW SPACING: a:b:a:b:c:b:a:b:a

2nd flr windows aligned

w/lst flr windows

WINDOW ORIENTATION:

lst flr: vertical
2nd flr: vertical

WINDOW TRIM AND SIZE:

5" jamb & head trim

DORMERS: No

SIDING MATERIAL:

horizontal wood siding

ROOF PITCH: 7:12

ROOF MATERIAL: Tin

ROOF TYPE: Gable, open

on East/West &

North/South axis

GABLE & EAVE TRIM:

fascia with molded

cornice

START OF EAVE:

Above 2nd flr



SET BACK FROM CTR LINE OF STREET: House: 40' 0"

CONSTRUCTION TYPE: Wood frame on

masonry foundation

FRONT PORCH: No

LOCATION OF PRIMARY ENTRANCE:
South facade/Street facade

GARAGE: Detached

DOORS/WINDOWS

PER FLOOR: 1st flr: 3

2nd flr: 2

WINDOW TYPE: 1st flr: double-hung

2nd flr: double-hung

PROPORTION

OF WINDOWS: (Vertical: Horizontal)

lst flr - 3:2 2nd flr - 3:2

WINDOW SPACING: a:b:a:b:a:b:a

2nd flr windows aligned

w/lst flr windows

WINDOW ORIENTATION:

lst flr: vertical
2nd flr: vertical

WINDOW TRIM AND SIZE:

4" jamb & head trim

DORMERS: No

SIDING MATERIAL:

horizontal cedar

shingles

ROOF PITCH: 7:12

ROOF MATERIAL:

Asphalt shingles

ROOF TYPE: Gable, open

on East/West axis

GABLE & EAVE TRIM:

fascia and molded

cornice

START OF EAVE:

Above 2nd flr window heads



41 FRALEIGH STREET

OF FLOORS ABOVE GRADE: 1 1/2

SET BACK FROM CTR LINE OF STREET: House: 40' 0"

CONSTRUCTION TYPE: Wood frame on masonry foundation

FRONT PORCH: No

LOCATION OF PRIMARY ENTRANCE:
South facade/Street facade

GARAGE: Detached

DOORS/WINDOWS
PER FLOOR: 3

WINDOW TYPE: double-hung w/
double-hung picture
window combination

PROPORTION

OF WINDOWS: (Vertical:Horizontal)
double hung- 2 1/2 :2
combination- 1 :2

WINDOW SPACING: a:b:a:c:d:e:d

WINDOW ORIENTATION:

double hung: vertical combination: horizontal

WINDOW TRIM AND SIZE:
1 1/2" jamb & head
trim

DORMERS: No

SIDING MATERIAL:
horizontal wood
siding

ROOF PITCH: 10:12

ROOF MATERIAL:
Asphalt shingles

ROOF TYPE: Gable - open on East/West axis

GABLE & EAVE TRIM: metal flashing & drip

START OF EAVE:
Above 1st flr
window heads



SET BACK FROM

CTR LINE OF STREET: Porch: 30' 0"

House: 36' 0"

CONSTRUCTION TYPE: Wood frame on

masonry foundation

FRONT PORCH: Yes - raised

LOCATION OF PRIMARY ENTRANCE:

South facade/Street facade

GARAGE: Detached

DOORS/WINDOWS

PER FLOOR: 1st flr: 3

2nd flr: 3

WINDOW TYPE: 1st flr: double-hung

2nd flr: awning

PROPORTION

OF WINDOWS: (Vertical: Horizontal)

1st flr - 2:1

2nd flr - 1 1/2:1

WINDOW SPACING: a:b:a:b:a:b:a

2nd flr windows aligned

w/lst flr windows

WINDOW ORIENTATION:

1st flr: vertical
2nd flr: horizontal

WINDOW TRIM AND SIZE:

4" jamb & head trim

- shutters

DORMERS: No

SIDING MATERIAL:

horizontal wood

siding

ROOF PITCH: 4:12

ROOF MATERIAL: Tin

ROOF TYPE: Hip

GABLE & EAVE TRIM:

Fascia w/ molded

cornice

START OF EAVE:

Above 2nd flr





SURVEY TOTALS

I OF FLOORS ADOVE SDADE	GIDING WINDDING
# OF FLOORS ABOVE GRADE:	SIDING MATERIAL:
One Story: 2	horizontal wood
Two Story: 7	siding: 7
Two Story	
w/ attic: 5	horizontal asbestos
CHE DIGY TROY	composite siding: 4
SET BACK FROM	
CTR LINE OF STREET:	horizontal cedar
	shingles: 1
North Side -	
Porch: 27' 0" to 30' 0":	3 horizontal aluminum
39' 0":	siding: 2
House: 33' 0" to 40' 0":	5
44' Ø":	1
South Side -	
Porch: 34' 0" to 40' 0":	2
40' 0" to 50' 0":	5
House: 25' 0":	1
30' 0" to 40' 0":	2
45' 0" to 50' 0":	5
CONSTRUCTION TYPE:	
Wood frame on	
masonry foundation: 14	
FRONT PORCH: Yes: 11	
No: 3	
LOCATION OF PRIMARY ENTRANCE:	
Street facade:	13
GARAGE: Detached: 11	
No garage: 3	
DOORS/WINDOWS	
PER FLOOR:	
First Floor	
Two - 1	
Three- 12	
Five - 1	

Second Floor Two - 3

Three- 8 Four - 1

WINDOW TYPE:	10:12 - 1
First floor	12:12 - 1
double hung: 13	PROPORTION OF WINDOWS:
combination: 1	(Vertical: Horizontal)
(double hung/	First floor
picture window)	2:1 - 8
	3:2 - 4
Second floor	2 1/2:2 - 1
double hung: 8	5:3 - 1
awning : 3	
combination: 1	Second floor
(double hung)	1:2 - 2
	1 1/2:2 - 1
	2:1 - 5
WINDOW SPACING:	3:2 - 4
2nd floor windows aligned	
w/lst flr windows: 11	WINDOW ORIENTATION:
	First floor
2nd floor windows	vertical: 13 1/2
NOT aigned w/lst flr	horizontal: 1/2
windows:	110222011642
	Second floor
No 2nd story windows: 2	vertical: 9
	horizontal: 3
	no 2ndstory: 2
WINDOW TRIM AND SIZE:	2
First flr & Second Flr	
4"-6" jambs	GABLE & EAVE TRIM:
and heads: 7	Fascia w/molded cornice: 11
and neads,	Metal flashing w/ drip: 2
4"-6" jambs	Covered:
w/molded	
heads: 5	START OF EAVE:
	Above 1st flr
1"-2" jamb	window heads: 2
and heads: 2	Tana on noda o
	Above 2nd flr
shutters: 4	window heads: 12
DORMERS: None: 14	ROOF TYPE:
	E/W: 5 \
	Gable: $N/S: 3 > 12$
ROOF MATERIAL:	both: 4 /
(material comprising	,
amount/house roof)	Hip:
Asphalt shingle: 9	
Tin: 5	Combination
, , , , , , , , , , , , , , , , , , ,	Hip/Gable: 1
ROOF PITCH:	
4:12 - 1	
7:12 - 7	
8:12 - 4	
V	