




C. H. CURTISS & CO.

HARDWARE,

PLUMBING & TINNING.

STEAM, HOT WATER AND HOT AIR HEATING.

Tarrytown, N.Y. August 3, 1898

Mr. W. H. Mersereau,

Dear Sir:-

While our men were working on the stable
at Sunnyside
drains, they were informed that the kitchen waste pipe was stopped.

We cleared out the grease trap, and found a quantity of sand in it; also the drain pipe from the two north lavatories was choked with sand, stopping it entirely. Upon making an investigation to learn where this sand came from, we found that a surface drain had been connected with this pipe since we put it in/ and as it could not carry the volume of water which came through the surface drain, it backed up into the grease trap, and into the branch from the lavatories, and lodged the sand there. This surface drain ought to be disconnected, and an independent pipe run for it.

Yours truly,

C. H. Curtiss & Co.

August 3,

Mr. W. H. Merseman,

Dear Sir:-

While our men were working on the stable drains, they were informed that the kitchen waste pipe was stopped. We cleared out the grease trap, and found a quantity of sand in it; also the drain pipe from the two north lavatories was choked with sand, stopping it entirely. Upon making an investigation to learn where this sand came from, we found that a surface drain had been connected with this pipe since we put it in and as it could not carry the volume of water which came through the surface drain, it backed up into the grease trap, and into the branch from the lavatories, and lodged the sand there. This surface drain ought to be disconnected, and an independent pipe run for it.

Yours truly,