

W. ADDISON BURNHAM,
PRESIDENT.
WARREN B. CRAW,
TREASURER.
LINCOLN PIERSON,
SECRETARY.
HENRY F. LORD,
SUPERINTENDENT.
ANDREW ELDER,
SUPT OF ERECTION.

LORD & BURNHAM COMPANY,
HORTICULTURAL ARCHITECTS & BUILDERS,
STEAM & HOT WATER HEATING ENGINEERS.

GENERAL OFFICE & WORKS,
IRVINGTON-ON-HUDSON, N.Y.

NEW YORK OFFICE,
ST. JAMES BLDG, B'WAY & 26TH ST.

ESTABLISHED 1856.

ALL ESTIMATES SUBJECT TO ACCEPTANCE
WITHIN TEN DAYS.

IRVINGTON-ON-HUDSON, N.Y.

Sept. 6, 1898.

W. H. Mersereau, Esq., Architect,
32 Broadway,
N. Y.

Dear sir:-

Referring again to the foot note in your favor of July 12th requesting us to enlarge the tube in leader outlet of gutter in Sunnyside Conservatory, our superintendent of Erection called there last week and we quote below his report:-

"I was up to Sunnyside this P. M. Some one has taken away the leader that we put up. I found the outlet from gutter stopped with leaves and rubbish and the gutter filled with water. I think the outlet is large enough and a large leader pipe would be very unsightly".

Trusting that this explanation will be found satisfactory,
we remain,

Yours truly,

LORD & BURNHAM CO.

Warren B. Caw
Treas.

Sept. 6, 1888

W. H. Harbison, Esq., Architect,
38 Broadway,
N. Y.

Dear Sir:-

Referring again to the foot note in your favor of July 18th
requesting us to enlarge the tube in leader outlet of gutter in Sunnyside
reservatory, our superintendent of erection called there last week and
quote below his report:-

"I was up to Sunnyside this P. M. Some one has taken
away the leader that we put up. I found the outlet
from gutter stopped with leaves and rubbish and the
gutter filled with water. I think the outlet is large
enough and a large leader pipe would be very unsightly."

Trusting that this explanation will be found satisfactory.

We remain,

Yours truly,

JORD & BURNHAM CO.