

to avoid staining the Caen Stone, therefore
the delay is probably caused by the shipment
from N.Y. Ordinary Cement would stain
the Caen Stone badly. — They probably are
there today.

In regard to Hall fireplace I think if
any thing, the opening is too high being
made 3' 6" against my judgement. — The
Jopuns Co. make an ashcatcher screen on a roller
that can be put back of arch out of sight.
& can be pulled down when fire is started
6 to 8" this would increase draft. as flue
is built exactly like Billiard Room & Library
defect is not there. — but in either height of
chimney, or in height of opening.

Yours very Sincerely
J. M. Mendenhall

the delay is probably caused by the shipmen
from Mr. O'Brien's current worked out
the coin store badly. — They probably are
they appear to have suffered a little of
the opening to high lying
any thing, against my judgment. — The
under 30,000, or thereabouts occur. in a well
John Co. make an attempt occur. in a well
that can be put out of sight.
I can be pulled down when fire is started
of 8" this would increase draft as firing
is built exactly like Belvidere from 1840
defect is not there — but in other parts of
evening. or a night of opening.
John Co. from my burning
J. H. H.