

you getting estimates, etc. etc. —
not on all work over 1000. money
change 5%. I trust this will be
satisfactory to you.

Yours truly
Allan Form

Payments as follows —

1%	on completion of Sketches
1 1/2	" " of Working Plan & spec.
1 1/4	" " of Details
1 1/2	" " of Supervision

5% total. —

gettin' rats etc. etc.
put on our own
breeds 2%
of the
the

[illegible]